DGM Aircraft / Justice Air Maintenance

9100 Republic Airport Farmingdale, NY 11735 US +16312704144 diana@justiceair.com





## **INVOICE**

**BILL TO** 

Avi Aspire Aviation 1100 New Highway Farmingdale, NY 11735 INVOICE # 2425

DATE 11/07/2024

DUE DATE 11/17/2024

TERMS Net 10

ACTIVITY	DESCRIPTION	RATE	AMOUNT
Cessna 172 100 Hr Inspection	N8184G - 100 HR inspection plus AD research and compliance. 100 Hour inspection accomplished I/A/W Cessna service man and FAR 43 Apdx D.	900.00	900.00
Flight School Labor Rate	N8184G - Multiple squawks found during inspection.  - Upon aircraft inspection found large gouge on propeller leading edge. Measurements found out of limits.  Removed and replaced propeller with overhauled P/N: 1C160/DTM7557M1 S/N: 734523 I/A/W Cessna service manual. Approved for return to service. (2.5 hr)  - During inspection found air duct from exhaust shroud to cabin heat worn and ripped.  Removed and installed new air duct. (0.5 hr)  - During inspection found left side exhaust stack clamps with corroded hardware and evidence of exhaust leak. Requires replacement.  Removed and installed new hardware I/A/W Cessna service manual. (1.0 hr)  - During inspection found starter wire needs to be rerouted, starting to chafe.  Loosened clamp for starter wire, rerouted wire and tightened clamp. (0.5 hr)  - During inspection found flexible baffle seals with fasteners missing.  Installed new baffle fasteners for flexible baffle. (0.5 hr)  - During inspection found cabin ventilation duct on right wing torn (Overhead vents).  Removed damaged duct and installed new duct IAW Cessna maintenance manual. (1.5 hr)  - During inspection found missing one flap button on right flap.	95.00	617.50

ACTIVITY	DESCRIPTION	RATE	AMOUNT	
	Installed flap button on right wing flap IAW Cessna service manual. (No additional labor charge) - During inspection found CO-detector expired. Installed a new ASA carbon monoxide detector expiration date Nov 6 2025. (No additional labor)			
Parts	Tempest oil filter	40.00	40.00	
Parts	Metal check oil analysis kit	30.31	30.31	
Parts	Aero Shell 15W-50 oil	14.00	84.00	
Parts	Air filter	16.67	16.67	
Parts	Carbon monoxide detector	3.42	3.42	
Parts	Duct	22.41	22.41	
Parts	Spark plug	55.20	441.60	
Parts	RTV Sealant	12.59	12.59	
Parts	Instrument filter	3.39	3.39	
Shipping and Freight Charges	Shipping for instrument not used beck to vendor	32.60	32.60	
Parts	Propeller inspection	180.00	180.00	
Parts	Miscellaneous hardware	13.43	13.43	
Parts	20% Re-stocking fee for instrument after 30 days	110.00	110.00	
Shop Supplies	Consumables & shop supplies	25.00	25.00	
Shipping and Freight Charges	Shipping for propeller overhaul	322.46	322.46	
Shipping and Freight Charges	Shipping for propeller back to DGM	124.34	124.34	
	BALANCE DUE	\$2	\$2,979.72	