Preliminary Invoice



8100 Republic Airport Farmingdale, NY 11735 United States March 18, 2024

Telephone: 631-756-5500 Fax: Maint@ventura.aero

Exchange Rate:

Bill To: Aspire Aviation LLC

1100 New Hwy

Farmingdale, NY 11735

1.000000 USD

Previous Billing:

INVOICE SUMMARY FOR WORK ORDER NUMBER: NY1120

United States

Invoice Number: INV24-00150

Invoice Date: 03/18/2024

Account Code: ASPIRE AVIATION LLC

P.O. Number:

Job Number:

-12,845.00 USD

Payment Type: Cash Payment Terms:

Registration Number: N433SP

Time & Materials Flat Rate Total Labor: 5,343.75 USD 5,343.75 USD Parts: 19,673.84 USD 19,673.84 USD Freight: 65.00 USD 65.00 USD Total: 25,082.59 USD 25,082.59 USD 0.00 USD **Avionics Consumables** 250.00 USD Subtotal: 25,332.59 USD

Total: 12,487.59 USD

WorkOrderPreliminaryInvoice.rpt 1 Printed on 03/18/2024 at 1:07:28PM

Preliminary Invoice



8100 Republic Airport Farmingdale, NY 11735 **United States**

March 18, 2024

Telephone: 631-756-5500 Fax: Maint@ventura.aero

WO #: NY1120 Invoice Number: INV24-00150 Bill To: Aspire Aviation LLC

Item: 1 Airframe Part/Model #: 172S

Item Serial Number:

Registration Number: N433SP Aircraft Serial Number: 172S8301

Discrepancy: 1.1 Install GTN750Xi w/ integration to existing CDI and Autopilot

T: 957.6 H: 1188.4

Resolution: Installed GTN750Xi S/N: 5FR052675 IAW Garmin STC SAA02019SE-D per 337 Dated 3/18/2024.

	Time & Materials	Flat Rate	Total
Labor:	4,680.00 USD		4,680.00 USD
Parts:	19,673.84 USD		19,673.84 USD
Freight:	65.00 USD		65.00 USD
Total:	24.418.84 USD	0.00 USD	24,418,84 USD

Parts:

Ref. No.	Part number	Description	Quantity	Sell price	Extended
1.1 #1	010-02002-05	GTN 750Xi Black GPS/COM/NAV receiver w/rack, backplate, conn kit, config module and product information kit	1.00	19,070.00 USD	19,135.00 USD
		Serial Number(s) 5FR052675			
			Freight:	65.00 USD	
1.1 #2	013-00235-00	GA™ 35 GPS Antenna, White	1.00	370.00 USD	370.00 USD
		Serial Number(s) 230935			
1.1.5 #1	7277-2-5	CIRCUIT BREAKER - 5 AMP	2.00	25.81 USD	51.62 USD
1.1.9 #1	ZFSC-2-1B	SPLITTER - 2 WAY NAV SPLITTER (-1 is no mtg. plate, 2 holes only	1.00	135.32 USD	135.32 USD
1.1.9 #2	RFT1202-C1	in body) TNC Male Crimp Connector - RG400 **********Primary p/n***********************************	2.00	9.32 USD	18.64 USD
1.1.9 #3	225395-6	BNC MALE CRIMP CONNECTOR - RG 400 ***********************************	2.00	4.39 USD	8.78 USD
1.1.9 #4	RFB1110-C1	BNC MALE 90° CRIMP CONNECTOR - RG400 *******Primary p/n********	1.00	19.48 USD	19.48 USD

1.2 Discrepancy: Remove #1 NAV/COM and ADF

Resolution: Removed original KX155 #1NAV/COM and KR-87 ADF. Equiment list updated

	Time & Materials	Flat Rate	Total
Labor:	247.50 USD		247.50 USD
Total:	247.50 USD	0.00 USD	247.50 USD

Preliminary Invoice



8100 Republic Airport Farmingdale, NY 11735 United States March 18, 2024

Telephone: 631-756-5500 Fax: Maint@ventura.aero

Bill To: Aspire Aviation LLC **WO #:** NY1120 **Invoice Number:** INV24-00150

Discrepancy: 1.3 Relocate XPDR to copilot panel

Resolution: Stratus ESG transponder relocated from center radio stack to copilot panel. Transponder software updated to FPGA P/N:

501010-000109 R07 per Appareo Service Bulletin No: 600870-000042. Data correspondence test good.

 Labor:
 416.25 USD
 Flat Rate
 Total

 Total:
 416.25 USD
 -- 416.25 USD

Form 9703 v204