Justice Air Maintenance

9100 Republic Airport Farmingdale, NY 11735 US (631) 465-0138 diana@justiceair.com





INVOICE

BILL TO INVOICE 1742 Avi DATE 11/06/2023 Aspire Aviation **TERMS** Net 10 1100 New Highway DUE DATE 11/16/2023 Farmingdale, NY 11735

| ACTIVITY | DESCRIPTION | QTY | RATE | AMOUNT |
|---------------|--|------|--------|----------|
| Shop supplies | Lord shimmy dampener | 1 | 999.65 | 999.65 |
| Aircraft Part | ELT Battery | 1 | 77.63 | 77.63 |
| Labor Rate | N8184G - Customer reported excessive shimmy during landing. Inspected and found shimmy dampener leaking. Attempted to overhaul with new o rings but shaft stuck inside. Removed and replaced shimmy damper with new upgrade Lord. (2.0 hr) - Customer reported pilot door pops open. Troubleshoot door lock. Opened and closed door multiple times, lubricated lock mechanics and were unable to duplicate fault. Owner notified (0.5 hr) - Customer reported AFT nav light inop. During inspection found right and AFT nav light bulbs burned. Replaced bulbs with new.(0.5 hr) - Customer requested ELT Battery to be replaced. Removed and replaced new battery. New battery EXP. date JAN 2026. (0.5 hr) | 3.50 | 95.00 | 332.50 |
| WO#534 | PAYMENT | | | 1,409.78 |

\$0.00 BALANCE DUE

PAID