## INVOICE

DGM Aircraft / Justice Air Maintenance 9100 Republic Airport Farmingdale, NY 11735 diana@justiceair.com +1 (631) 270-4144





Bill to

Avi Aspire Aviation 1100 New Highway Farmingdale, NY 11735 Ship to
Avi
Aspire Aviation
1100 New Highway
Farmingdale, NY 11735

Invoice details

Invoice no.: 2598 Terms: Net 10

Invoice date: 01/24/2025 Due date: 02/03/2025

	Product or service	Description	Qty	Rate	Amount
. i	Flight School Labor Rate	N9863L	11.5	\$100.00	\$1,150.00
	·	- Left aileron requires replacement due to		•	
		deformation on top inboard of aileron.			
		Removed LH aileron. Primed, painted and			
		installed overhauled aileron IAW Cessna			
		service manual. (4.0 hr)			
		- During inspection found cowling mount			
		broken/ missing.			
		Removed and replaced missing cowling			
		mount IAW Cessna service manual. (0.5 hr)			
		- Left flap removed to be installed on			
		N433SP.			
		Flap removed and installed on N433SP.			
		Overhauled flap was ordered. During the			
		removal of flap found two inboard flap track			
		brackets with small cracks. Replaced			
		brackets with new. Primed and painted left			
		flap and installed with new roller kit. All work			
		performed in reference to Cessna service			
		manual. (6.0 hr)			
		- Right wing fuel tank found with crack.			
		Right wing fuel tank repaired I/A/W AC			
		43.13-1B. No further leaks. (1.0 hr)			
. 1	Parts	Left flap assembly	1	\$4,244.20	\$4,244.20
. 1	Parts	Flap roller kit	1	\$448.12	\$448.12
. 1	Parts	Lord cowl mount	1	\$100.37	\$100.37

5.	Shipping and Freight Charges	Shipping for aileron	1	\$759.66	\$759.66
6.	Shipping and Freight Charges	Outbound shipping for aileron core	1	\$759.66	\$759.66
7.	Shipping and Freight Charges	Shipping for flap assembly	1	\$506.70	\$506.70
8.	Shipping and Freight Charges	Outbound shipping for flap assembly core	1	\$579.01	\$579.01
9.	Shop Supplies	Consumables & shop supplies	1	\$50.00	\$50.00

Total \$8,597.72

## Ways to pay



Note to customer WO#1177