DGM Aircraft / Justice Air Maintenance

9100 Republic Airport Farmingdale, NY 11735 US +1 6312704144 diana@justiceair.com





INVOICE

 BILL TO
 INVOICE
 2276

 Avi
 DATE
 08/27/2024

 Aspire Aviation
 TERMS
 Net 10

 1100 New Highway
 DUE DATE
 09/06/2024

 Farmingdale, NY 11735

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Piper 50 HR Inspection	N433SP - 50 HR Inspection.	1	250.00	250.00
Flight School Labor Rate	 N433SP Pilot reported landing light inop during pre flight inspection. During troubleshoot discovered blow landing light bulb. Removed and replaced landing light bulb with new IAW AMM. Ops check OK, landing light illuminates. (1.0 hr labor) During inspection found bold spot on LH main landing gear tire. Removed and replaced LH MLG tire and tube with new IAW AMM. (1.0 hr labor) Right hand main landing tire worn beyond limits. Removed and replaced RH MLG tire and tube with new IAW AMM. (1.0 hr labor) Left hand strobe light inop needs to be replace. Troubleshot and found strobe power supply inop. Removed and replaced strobe power supply for new model. (2.0 hr labor) Customer reported excessive deviation on directional gyro. Checked vacuum system connections and found ok. Performed run up and taxi and unable to duplicate. (1.0 hr labor) Customer reported magnetic compass is off. Unable to check on ground. Informed owner that a compass swing is needed to verify and recommend avionics shop. (No additional labor charge.) AMP meter requires installation with new unit. Removed serviceable (loaner instrument) and replaced with new vacuum and amp gauge. (1.0 hr labor) 	7	95.00	665.00
Parts	Phillips 20W-50	7	12.00	84.00
Parts	Tempest 110 oil filter	1	40.00	40.00
Parts	Oil analysis kit	1	30.31	30.31
Parts	Air Hawk Tire	2	143.75	287.50
Parts	Leakguard inner tube	2	124.02	248.04
Parts	Bulb	1	14.89	14.89

Parts	Cotter pin	2	0.25	0.50
Parts	Whelen power supply	1	960.52	960.52
Parts	Vacuum/amp indicator	1	1,236.25	1,236.25
Parts	Vacuum/pump core charge (Powerpacks plus)	1	1,500.00	1,500.00
Parts	Inspection for vacuum amp gauge (not repairable)	1	46.00	46.00
Shipping and Freight Charges	Shipping for amp out for inspection	1	18.18	18.18
Shipping and Freight Charges	Shipping for amp core back to DGM	1	20.50	20.50
Shipping and Freight Charges	Shipping for amp gauge	1	48.21	48.21
Shipping and Freight Charges	Shipping core back to vendor	1	23.00	23.00
Shop Supplies	Consumables & shop supplies	1	25.00	25.00

 ⁻ Vacuum/Amp core was sent to Powerpacks plus for second evaluation.
 If the core Is repairable they will refund the core charge.
 WO# 887 & 905

\$5,497.90