Justice Air Maintenance

9100 Republic Airport Farmingdale, NY 11735 US (631) 465-0138 diana@justiceair.com





INVOICE

 BILL TO
 INVOICE
 1737

 Avi
 DATE
 11/06/2023

 Aspire Aviation
 TERMS
 Net 10

 1100 New Highway
 DUE DATE
 11/16/2023

 Farmingdale, NY 11735
 Termingdale
 11/16/2023

ACTIVITY	DESCRIPTION		QTY	RATE	AMOUNT
7.0117111	DEGGINI HON		QTT	TOTIL	AMOONT
Aircraft Part	LH Inboard seat rail (shipping include	d)	1	633.85	633.85
Labor Rate	N9863L - Owner reports left door locks when closed from outside. Removed, re adjusted locking mechanism and performed operational check satis. (No additional labor charge) - Pilot reports unable to lock left pilot seat properly in seat track. Troubleshot and found left pilot inboard seat track installed misaligned. Requires replacement. Part ordered. Replaced pilot seat inboard track with new. (8.0 hr) - Customer reported carb heat inop. During troubleshoot found carburetor heat house disconnected. Noticed that the carb box for hot air duct broken off. Removed carb heat box to be welded. Reinstalled carb heat box and engine run up satis. (3.0 Hr)		11	95.00	1,045.00
Service	Carburetor air box welding repair.		1	250.00	250.00
WO#532	F	PAYMENT			1,928.85
	E	BALANCE DUE			\$0.00

PAID