Preliminary Invoice



8100 Republic Airport Farmingdale, NY 11735 United States July 02, 2025

Telephone: 631-756-5500 Fax: Maint@ventura.aero

Invoice Number: INV25-00306

Bill To: Aspire Aviation LLC

1100 New Hwy

Farmingdale, NY 11735

United States

Account Code: ASPIRE AVIATION LLC
P.O. Number:

Job Number:

Payment Type: Cash Payment Terms: Invoice Date: 07/2/2025

Exchange Rate: 1.000000 USD

INVOICE SUMMARY FOR WORK ORDER NUMBER: NY1870 Registration Number: N64527

	Time & Materials	Flat Rate	Total
Labor:	293.75 USD		293.75 USD
Total:	293.75 USD	0.00 USD	293.75 USD
Subtotal:			293.75 USD
Totalı			203 7E USD

Total: 293.75 USD

WorkOrderPreliminaryInvoice.rpt 1 Printed on 07/02/2025 at 6:10:41PM





8100 Republic Airport Farmingdale, NY 11735 United States July 02, 2025

Telephone: 631-756-5500 Fax: Maint@ventura.aero

Bill To: Aspire Aviation LLC **WO #:** NY1870 **Invoice Number:** INV25-00306

Item: 1 Airframe Part/Model #: 172M

Item Serial Number:
Registration Number: N64527

Aircraft Serial Number: 17265283

Discrepancy: 1.1 Oil leaking from Oil pressure line fitting from accessory case.

T:3194.4 H:1092.9

Resolution: Relocated Oil pressure fitting on accessory case and plugged existing port. Cleaned back of engine, belly of aircraft, and performed

ground runs with no leaks detected.

 Labor:
 293.75 USD
 -- 293.75 USD

 Total:
 293.75 USD
 0.00 USD
 293.75 USD