Preliminary Invoice



8100 Republic Airport Farmingdale, NY 11735 United States April 09, 2025

Telephone: 631-756-5500 Fax: Maint@ventura.aero

Bill To: Aspire Aviation LLC

1100 New Hwy

Farmingdale, NY 11735

United States

Invoice Number: INV25-00130

Account Code: ASPIRE AVIATION LLC **P.O. Number:**

Job Number:

Payment Type: Cash Payment Terms: Invoice Date: 04/9/2025

Exchange Rate: 1.000000 USD

INVOICE SUMMARY FOR WORK ORDER NUMBER: NY1721 Registration Number: N388JF

	Time & Materials	Flat Rate	Total
Labor:	690.00 USD		690.00 USD
Total:	690.00 USD	0.00 USD	690.00 USD
Subtotal:			690.00 USD

Total: 690.00 USD





8100 Republic Airport Farmingdale, NY 11735 United States April 09, 2025

Telephone: 631-756-5500 Fax: Maint@ventura.aero

Bill To: Aspire Aviation LLC **WO #:** NY1721 **Invoice Number:** INV25-00130

Item: 1 Airframe Part/Model #: 172P

Item Serial Number:

Registration Number: N388JF Aircraft Serial Number: 17276182

Discrepancy: 1.1 Foward Upper Cowl Bowl Damaged

Resolution: Repaired Fiberglass On Center Attached Points Of Forward Upper Cowl Bowl And Reinstalled.

Time & Materials Flat Rate Total

2

Labor: 690.00 USD --- 690.00 USD

Total: 690.00 USD 0.00 USD 690.00 USD

Item: 2 Misc Part/Model #:

Item Serial Number: N/A Registration Number: N388JF Aircraft Serial Number: 17276182

Discrepancy: 2.1 Hobbs Time

Resolution: Hobbs 4544.1