DGM Aircraft / Justice Air Maintenance

9100 Republic Airport Farmingdale, NY 11735 US +1 6312704144 diana@justiceair.com

Farmingdale, NY 11735





INVOICE

BILL TO INVOICE 2257
Avi DATE 08/26/2024
Aspire Aviation TERMS Net 10
1100 New Highway DUE DATE 09/05/2024

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Flight School Labor Rate	 N8184G Customer reported taxi and landing lights inop. Removed top cowling and taxi light access panel. Found taxi light power output wire damaged & not connected. Removed and replaced wire with new. Re-installed panel and performed OPS check. OPS check good. (1.0 hr labor) Customer reported left magneto drop is excessively low. Removed top cowling and inspected magneto P lead & ground wires for any damage or loose connections. Performed magneto timing check IAW Cessna service manual section 11 and timed both mags to engine. Ran engine and checked for proper Magneto Drop. Drop was found within limits and not further leaks were found in the engine. (1.5 hr labor) Found top cowling fasteners missing. Installed new cowling fasteners & retainer washers and installed cowling back to engine. (0.5 hr labor) 	3	95.00	285.00
Parts	Fastener	2	1.43	2.86
Parts	Retainer	2	0.25	0.50
Parts	1FT wire	1	3.00	3.00