Preliminary Invoice

VENTURA
AVIATION | MOBILE AIRCRAFT SERVICES | AVIONICS

March 31, 2025

8100 Republic Airport
Farmingdale, NY 11735
United States

Telephone: 631-756-5500   Fax: Maint@ventura.aero

|..||..|||..|.|||..|.|..|||..|.||.|

Bill To: Aspire Aviation LLC

1100 New Hwy
Farmingdale, NY 11735
United States

Payment Type: Cash   **Payment Terms:**

Exchange Rate: 1.000000 USD

INVOICE SUMMARY FOR WORK ORDER NUMBER: NY1708

Invoice Number: INV25-00122

Account Code: ASPIRE AVIATION LLC

P.O. Number:

Job Number:

Invoice Date: 03/31/2025

Registration Number: N433SP

	Time & Materials	Flat Rate	Total
Labor:	284.40 USD	---	284.40 USD
Parts:	133.81 USD	---	133.81 USD
Total:	**418.21 USD**	**0.00 USD**	**418.21 USD**
Subtotal:			418.21 USD
Total:			**418.21 USD**

Preliminary Invoice

VENTURA
AVIATION | MOBILE AIRCRAFT SERVICES | AVIONICS

March 31, 2025

8100 Republic Airport
Farmingdale, NY 11735
United States

Telephone: 631-756-5500   Fax: Maint@ventura.aero

Bill To: Aspire Aviation LLC	**WO #:** NY1708	**Invoice Number:** INV25-00122

Item: 1 Skyhawk

Part/Model #: 172S
Item Serial Number:
Registration Number: N433SP
Aircraft Serial Number: 172S8301

Discrepancy: 1.1   50 Hr Oil And Oil Filter Change

Resolution: Serviced engine with 8 quarts of 20w-50 X/C engine oil. Installed oil filter PN: 48110-2. Performed engine run up, mag check and leak check good.

	Time & Materials	Flat Rate	Total
Labor:	244.80 USD	---	244.80 USD
Parts:	132.56 USD	---	132.56 USD
Total:	**377.36 USD**	**0.00 USD**	**377.36 USD**

Parts:

Ref. No.	Part number	Description	Quantity	Sell price	Extended
1.1 #1	20W-50	OIL - PHILLIPS 66 X/C Aviation SAE 20W-50	8.00	*Multiple*	83.94 USD
1.1 #2	AA48110-2	Oil Filter - Tempest	1.00	48.62 USD	48.62 USD

Discrepancy: 1.2   Tail av Light Inop

Resolution: Relamped Tail Nav Light With New PN 1683 Ops Check OK.

	Time & Materials	Flat Rate	Total
Labor:	39.60 USD	---	39.60 USD
Parts:	1.25 USD	---	1.25 USD
Total:	**40.85 USD**	**0.00 USD**	**40.85 USD**

Parts:

Ref. No.	Part number	Description	Quantity	Sell price	Extended
1.2 #2	1683	LIGHT BULB	1.00	1.25 USD	1.25 USD

Item: 2 Intake

Part/Model #:
Item Serial Number:
Registration Number: N433SP
Aircraft Serial Number: 172S8301

Discrepancy: 2.1   Hobbs Time

Resolution: Hobbs: 2006.5

Discrepancy: 2.2   Incoming Photos

Resolution: Completed Incoming Photos