INVOICE

DGM Aircraft / Justice Air Maintenance 9100 Republic Airport Farmingdale, NY 11735 diana@justiceair.com +1 (631) 270-4144





Bill to

Avi Aspire Aviation 1100 New Highway Farmingdale, NY 11735 Ship to
Avi
Aspire Aviation
1100 New Highway
Farmingdale, NY 11735

Invoice details

Invoice no.: 2591 Terms: Net 10

Invoice date: 01/17/2025 Due date: 01/27/2025

Product or service	Description	Qty	Rate	Amount
Flight School Labor Rate	N9863L	122.5	\$140.00	\$17,150.00
	- Customer reported right flap inboard			
	track with damage. Found during preflight			
	inspection.			
	During inspection found right inboard flap			
	track brackets broken and inboard flap			
	track loose. Upper and lower trailing edge			
	skins found with damage. Fuel tank was			
	removed for further inspection and found a			
	crack on AFT spar behind inboard flap			
	track. Notified Textron engineering and			
	provided layout of damage for repair			
	scheme. Performed repair to aft inboard			
	spar as per Textron Aviation engineering			
	document #DQ46941. NDT inspection			
	performed and no other damage noted.			
	Removed and replaced upper and lower			
	trailing edge skins with new. Replaced right			
	wing inboard rib with new. Replaced			
	inboard flap track brackets with new.			
	Reinstalled flap with new roller kit. Primed			
	and painted as required. All work			
	preformed in reference to Cessna service			
	manual and AC 43.13-1B. Logbook entry			
	and 337 formed accomplished.			
Parts	Upper trailing edge wing skin	1	\$581.76	\$581.76
Parts	Lower trailing edge wing skin	1	\$608.34	\$608.34

	Waye to nay		Total	\$22,044.63	
14.	Shop Supplies	Consumables & shop supplies	1	\$125.00	\$125.00
13.	Shipping and Freight Charges	Shipping for lower trailing edge wing skin	1	\$137.13	\$137.13
12.	Shipping and Freight Charges	Shipping for upper trailing edge wing skin and right wing inboard flap track rib	1	\$587.00	\$587.00
11.	Shipping and Freight Charges	Shipping for flap track brackets	1	\$35.00	\$35.00
10.	Services	RH Wing NDT inspection as per Textron Engineering	1	\$700.00	\$700.00
9.	Aircraft Part	McFarlane Flap roller kit (Includes shipping)	1	\$448.12	\$448.12
8.	Parts	Paint - Matterhorn White & Hardener/Activator (Includes shipping)	1	\$485.63	\$485.63
7.	Parts	Rivets	1	\$425.00	\$425.00
6.	Parts	Zinc phosphate primer	3	\$20.91	\$62.73
5.	Parts	Flap track brackets	2	\$143.61	\$287.22
4.	Parts	Right wing inboard flap track rib	1	\$411.70	\$411.70

Ways to pay



Overdue

01/27/2025

Note to customer WO1088