Justice Air Maintenance

9100 Republic Airport Farmingdale, NY 11735 US 6314650138 diana@justiceair.com





INVOICE

BILL TO

Avi Aspire Aviation 1100 New Highway Farmingdale, NY 11735 INVOICE # 2855

DATE 05/23/2025

DUE DATE 06/02/2025

TERMS Net 10

ACTIVIT	Y DESCRIPTION	QTY	RATE	AMOUNT	
Cessna 172 100 Hr Inspecti	•	1	900.00	900.00	
Flight School Labor Rate	N388JF - Multiple squawks found during inspection. - Customer reported a tail strike. Documented damage with photographs. Submitted a SDR report inquiry to Cessna for evaluation. Report included full damage description, image evidence, and request for structural inspection criteria and approved repair instructions and further inspections. Awaited response from Cessna engineering before performing further inspection or corrective action. Performed a thorough inspection of affected area no further damage found besides the tail scrape. Performed a doubler patch IAW the Cessna damage repair instructions. and lower tail repainted to match the rest of the aircraft. Rudder lower end found cracked. Removed and replaced rudder lower end cap with new. (29.0 hr) - During inspection found right top cowling 1/4 turn is loose. Upon further inspection found camloc missing. Removed and replaced sky bolt fastener (camloc) with new IAW Cessna service manual. (1.5 hr) - During inspection found oil dipstick gasket was leaking. Removed and replaced dipstick gasket with new IAW Lycoming service manual. (0.5 hr)	33.50	100.00	3,350.00	

ACTIVITY	DESCRIPTION	QTY	/ RATE	AMOUNT
	 During inspection found shimmy dar loose. Removed worn hardware and repl new hardware. All work done IAW Ce AMM. (1.0 hr) Right wing fuel quantity placard miss Installed new fuel quantity placard Cessna service manual and AC 43-13 additional labor charge) Owner reported Hobbs meter interm Performed troubleshoot and found wire broken. Repair broken wire OPS good. All work performed in reference and AC 43.13-1B. (1.0 hr) 	aced with ssna 172 sing IAW 3.1B. (No ittent. ground check		
Parts	Phillips 20W-50 oil	7	7 12.00	84.00
Parts	Tempest oil filter	•	40.00	40.00
Parts	Oil analysis kit	•	30.31	30.31
Parts	Air filter	•	12.00	12.00
Parts	Fuel placard	•	7.97	7.97
Parts	Eye bolt	•	291.32	291.32
Parts	Skybolt fastener	-	22.51	22.51
Parts	Lycoming oil dipstick gasket	•	1.84	1.84
Parts	890 B 1/2 Sealant / 6 oz SEM Kit	-	75.13	75.13
Parts	Cessna172 Rudder Butt Tip	•	118.15	118.15
Parts	Miscellaneous hardware	•	11.48	11.48
Shop Supplies	Consumables & shop supplies	•	50.00	50.00
Shipping Fee	Shipping for hardware	•	21.56	21.56
Shipping Fee	Shipping overnight for fastener	•	151.13	151.13
WO#1416	E	BALANCE DUE	E \$5,167.40	