Preliminary Invoice



8100 Republic Airport Farmingdale, NY 11735 United States July 02, 2025

Telephone: 631-756-5500 Fax: Maint@ventura.aero

Bill To: Aspire Aviation LLC

1100 New Hwy

Farmingdale, NY 11735

United States

Invoice Number: INV25-00305

Account Code: ASPIRE AVIATION LLC

P.O. Number:

Job Number:

Payment Type: Cash Payment Terms: Invoice Date: 07/2/2025

Exchange Rate: 1.000000 USD

INVOICE SUMMARY FOR WORK ORDER NUMBER: NY1863 Registration Number: N433SP

	Time & Materials	Flat Rate	Total	
Labor:		1,320.00 USD	1,320.00 USD	
Parts:	651.36 USD		651.36 USD	
Total:	651.36 USD	1,320.00 USD	1,971.36 USD	
Subtotal:			1,971.36 USD	
_				

Total: 1,971.36 USD





8100 Republic Airport Farmingdale, NY 11735 United States July 02, 2025

Telephone: 631-756-5500 Fax: Maint@ventura.aero

Bill To: Aspire Aviation LLC **WO #:** NY1863 **Invoice Number:** INV25-00305

Item: 1 Airframe Part/Model #: 172S

Item Serial Number:

Registration Number: N433SP **Aircraft Serial Number:** 172S8301

Discrepancy: 1.1 Oil Leak / High Oil Temp

Incoming T:1639.7, H:2141.6

Outgoing

T:1639.9 H:2142.1

Resolution: Operational check of Oil Temp Probe checked good. Installed New Vernatherm P/N:53E19600. Cleaned back of engine and performed

multiple ground runs with no leaks detected.

 Labor:
 -- 1,320.00 USD
 1,320.00 USD

 Parts:
 651.36 USD
 -- 651.36 USD

 Total:
 651.36 USD
 1,320.00 USD
 1,971.36 USD

Parts:

Ref. No.	Part number	<u>Description</u>	Quantity	Sell price	Extended
1.1 #2	53E19600	Valve	1.00	588.00 USD	588.00 USD
1.1 #4	J-7444-36	ENGINE COWLING MOUNT	1.00	63.36 USD	63.36 USD