Islip Avionics, Inc. 135 Schaeffer Dr. Ronkonkoma, NY 11779 US +16313386724 sales@islipavionics.com

www.islipavionics.com

Invoice



Aspire Aviation 1100 New Highway Farmingdale, NY 11735

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
10622	01/27/2025	\$4,445.00	02/26/2025	Net 30	

N# A/C S/N N388JF 17276182

DESCRIPTION		QTY	RATE	AMOUNT
Shop Labor- Performed software updates of GTN-760 / G 23065 to version 6.73. Performed software update of GDL via SB 23056. Performed data correspondence test to 5,0 airspeeds for accuracy. Troubleshot static leaks. Found be for both the pitot and static systems to the Aspen were pluclear/nylon tubing to be both leaking. Tubes loose on tees brass tees to nylon fittings and new tubes to airspeed for lisides. Also the existing nylon tube from altimeter to the englove box was no longer soft tube. The connection at the cracked and leaking. Removed and replaced Garmin GI-1 serviceable GI-106B. Corrected issue with autopilot - disp Replaced fuse via SB 14-005, Rev H. (*Note: Spent about charging 12 as courtesy)	12	180.00	2,160.00	
Serviceable Exchange Garmin GI-106B s/n D17-11525	1	2,250.00	2,250.00	
Misc Supplies (tees, nuts/sleeves, tubing, etc.)		1	35.00	35.00
We appreciate your prompt payment.	SUBTOTAL			4,445.00
Invoices not paid within terms are subject to a 1.5% monthly finance charge.	TAX		0.00	
mana analya	TOTAL			4,445.00
	BALANCE DUE		\$4	.445.00