Islip Avionics, Inc. 135 Schaeffer Dr.

Ronkonkoma, NY 11779 US (631)588-3543

sales@islipavionics.com www.islipavionics.com

BILL TO

Aspire Aviation 1100 New Highway Farmingdale, NY 11735





INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
10259	07/23/2024	\$6,518.00	08/22/2024	Net 30	

N# A/C S/N N64527 17265283

DESCRIPTION	QTY	RATE	AMOUNT
Perform Annual Inspection- Flat Rate. Includes the following: Check status of Airworthiness directives. Any required AD compliance inspections or repairs are not included in flat rate. Wash engine. Drain oil, Remove and inspect oil filter, Install new oil filter, service engine with oil (Oil and filter not included), Perform engine compression check, Clean spark plugs and check gap, check magneto timing, visually inspect engine, Visually inspect propeller and lubricate if appropriate, Open all airframe inspection panels as required. Visually inspect airframe. Lubricate airframe per manufacturers requirements, jack aircraft as needed, inspect tires and wheels, clean, inspect and lubricate wheel bearings, inspect brakes, Perform normal and emergency gear swings if appropriate, perform required inspection and functional test of ELT, inspect battery box and battery, inspect radios and instruments and complete appropriate paperwork.	1	2,000.00	2,000.00
Case of Oil and Filter, New, Includes Shipping	1	200.00	200.00
Shop Labor- Replaced carb heat scat tube with new.	0.50	150.00	75.00
Parts- Scat Tube	1	25.00	25.00
Shop Labor- Replaced exhaust and fairing with new short-stack from Power Flow, and Maple Leaf fairing. (*Note: Spent 10 labor hours, charging 8 as courtesy)	8	150.00	1,200.00
Short-Stack Exhaust, Power Flow, Replacement Kit	1	1,500.00	1,500.00
Maple Leaf Fairing Kit	1	500.00	500.00
Shipping Expense- Overnight	1	130.00	130.00
Misc Shop Supplies	1	25.00	25.00
Shop Labor- Address RPM erratic issue. Replaced buffer resistors for P-Lead interface to Dynon EMS. (*Note: Spent 2 labor hours, charging 1.5 as courtesy)	1.50	150.00	225.00
Parts- Resistors	1	5.00	5.00
Shop Labor- Replace baggage door latch spring with new. (*Note: Spent 2 labor hours, charging 1.5 as courtesy)	1.50	150.00	225.00
Parts- Latch Spring Kit (includes shipping)	1	40.00	40.00

DESCRIPTION		QTY	RATE	AMOUNT
Shop Labor- Complied with AD for Bendix Switch. Complied with AD for Seat Tracks. Complied with AD for AmerKing ELT.		2	150.00	300.00
Copper Spark Plug Gaskets		8	1.00	8.00
Air Filter Re-Charge Kit (includes shipping)		1	60.00	60.00
We appreciate your prompt payment.	SUBTOTAL			6,518.00
Invoices not paid within terms are subject to a 1.5%	TAX			0.00
monthly finance charge.	TOTAL			6,518.00
	BALANCE DUE	\$6,518.		