## INVOICE

**Justice Air Maintenance** 9100 Republic Airport Farmingdale, NY 11735 diana@justiceair.com +1 (631) 465-0138





Bill to

Avi Aspire Aviation 1100 New Highway Farmingdale, NY 11735 Ship to Avi Aspire Aviation 1100 New Highway Farmingdale, NY 11735

Invoice details

Invoice no.: 2663 Terms: Net 10

Invoice date: 02/21/2025 Due date: 03/03/2025

‡	Product or service	Description	Qty	Rate	Amount
۱.	Flight School Labor Rate	N9863L	2	\$100.00	\$200.00
		- Replacing flap Indicator notched placard.			
		Removed and replaced notched flap			
		indicator placard with new. During ops			
		check, discovered dirt interfering with			
		microswitch activation. Cleaned area and			
		actuator arm contacts and activated			
		microswitch properly. During ops check,			
		discovered cable that controls flap			
		indication not properly clamped, allowing			
		cable to slip from the flap lever arm,			
		preventing lever arm from actuating and			
		activating micro switch in the 10 degree			
		position intermittently. This was caused by			
		the nut bottoming out on threads before			
		providing enough clamping force to hold the			
		cable in place. Removed nut and added			
		hardware needed. Secured and adjusted			
		cable, verified indicated position matched			
		the actual position of the flaps. Ops check			
		OK. Flaps move reliably into 10 degrees,			
		and indicates the correct flap position			
		selected. (2.0 hr)			
2.	Parts	Flap cover	1	\$427.57	\$427.57
3.	Parts	Miscellaneous hardware	1	\$0.40	\$0.40
١.	Shop Supplies	Consumables & shop supplies	1	\$10.00	\$10.00

## Ways to pay



## Note to customer

WO#1246