LOC/DME I-OJP Rwy Idg 11601 APP CRS 110.7 TDŹE 92 005° Apt Elev 96 Chan 44

DME or RADAR required.

Simultaneous approach authorized

V

Δ

27 JAN 2022

ō


24 FEB

ILS RWY 36R (CAT II & III) ORLANDO INTL (MCO)

MISSED APPROACH: Climb to 500 then climbing left turn to 3000 on heading 309° and ORL R-248 to DNMOR/ORL 6 DME and hold, continue

Ŧ climb-in-hold to 3000 ORLANDO TOWER **GND CON** CLNC DEL 126.4 (East) 118.45 253.5 (Rwys 17L-35R,17R-35L) 134.7 (Rwys 18L-36R, 18R-36L) 121.8 (West) 124.3 253.5 341.7

ALSF-2



35L/R, and 36R ORLANDO, FLORIDA Amdt 11 12OCT17

TDZ/CL Rwys 17L/R, 18R,

ORLANDO INTL (MCO) ILS RWY 36R (CAT II & III)

& AIRCRAFT CERTIFICATION REQUIRED