SOUTH BEND, INDIANA AL-399 (FAA) 19339 WAAS 7101 RNAV (GPS) RWY 18 Rwy Idg APP CRS CH 73021 TDŹF 798 182° SOUTH BEND INTL (SBN) Apt Elev 798 W18A RNP APCH. MISSED APPROACH: Climb to V For uncompensated Baro-VNAV systems, LNAV/VNAV 2400 direct DRNAA and hold. NA below -19°C or above 54°C Δ ATIS SOUTH BEND APP CON★ SOUTH BEND TOWER★ GND CON CLNC DEL 135.675 (CTAF) 0 257.8 120,675 118.55 257.8 121.7 121.9 *№ 2500* 2500 1040 (IF) (IAF) 272° (18.6) LASÉA MAPÉR (IAF) (15.3)**JJANN** Procedure NA for arrivals at MAPER on V526 northwest bound. Procedure NA for arrivals at JJANN on V156 northeast bound and on V277 southeast bound. 2400 **182**° (10.1) (FAF) 930 1149 972 Λ Λ RW18 25 Nz **∧** RW18<u>@</u>**∧**897± 3000 960 Λ 1078 1949 MISSED APCH FIX ELEV 798 798 **TDZE** DRNAA 182° to **RW18** 4 NM 2400 DRNAA LASEA **TYLRR** 81 2500 1820 2400 **RW18** GP 3.00° 2400 TCH 50 _©g - 10 1 NM 4 9 NM С D CATEGORY LPV DA 1048-1 250 (300-1) 36 LNAV/ VNAV DA 1057-1 259 (300-1) 1160-1 362 (400-1) LNAV MDA HIRL Rwy 9R-27L 0 1440-13/4 1500-21/4 MIRL Rwy 18-36 (**C** CIRCLING 1280-1 482 (500-1) MIRL Rwy 9L-27R 642 (700-13/4) 702 (800-21/4)

SOUTH BEND, INDIANA Amdt 1B 13SEP18

SOUTH BEND INTL (SBN)

24 FEB 2022

٥,

27 JAN 2022

EC-2,