24 FEB 2022

2

27 JAN 2022

SE-3,

CICIV

LOC/DME I-VIN Rwy Idg 10220 APP CRS 109.1 TDŹE 272° Apt Elev 9 Chan 28 DME required. RNP APCH-GPS. From TUBBZ

Chan 118

Simultaneous approach authorized. Inop table does


not apply to S-ILS 26L all Cats. For inop ALS, increase

S-LOC 26L Cats A/B visibility to RVR 5500 and Cats C/D

ILS or LOC RWY 26L MIAMI INTL (MIA)

MISSED APPROACH: Climb to 800 then climbing MALSF right turn to 4000 on heading 290° and DHP (A₄) ---VÖRTAC R-335 to BRBRA/DHP 11.5 DME and hold, continue climb-in-hold to 4000.

visibility to RVR 6000. D-ATIS GND CON MIAMI APP CON MIAMI TOWER CLNC DEL ARR 119.15 121.8 (8L/8R/12/26L/26R) **CPDLC** 124.85 322.3 118.3 256.9 348.6 135.35 DEP 133,675 127.5 (9/27/30) NSA DHP 25 Ny 1049 **BRBRA** 2100 DHP 11.5 1049 270 090° 1049 2900 LOCALIZER 109.1 I-VIN ::--(IAF) ŻILBİ Chan 28 AGLER CON<u>ST</u> I-VIN |18) I-VIN 6.7 RADAR I-VIN 4.5 CIDUN RADAR ∧³²⁸ DOLPHIN RADAR I-VIN 14.6) 113.9 DHP ²⁴⁴^. RADAR Chan 86 170 (3.5) 3000 to BASHO (4.6)^253 1049± (12.2) (IF) ^293 **BASHO** (IAF) I-VIN 11.3 ALTERNATE MISSED APCH FIX V_{333} TUBBZ RADAR 6000 ...098°**►**... 117.1 VKZ -R-278-



HIRL all Rwys MIAMI, FLORIDA Amdt 17 12AUG21

TDZ/CL Rwy 8R REIL Rwys 8L and 26R

> MIAMI INTL (MIA) ILS or LOC RWY 26L

411 (500-1)

420/50

420/40 411 (500-34)

S-LOC 26L