EC-2,

27 JAN 2022

ō 24 FEB

AL-94 (FAA) 8000 WAAS Rwy Idg RNAV (GPS) Y RWY 10L APP CRS CH 40299 TDŹE 815 101° JOHN GLENN COLUMBUS INTL (CMH) Apt Elev 815 W10B RNP APCH MISSED APPROACH: For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -19°C or above 54°C. MALSR Climb to 1400 then LNAV procedure NA during simultaneous operations. Use of FD or AP providing climbing left turn to RNAV track guidance required during simultaneous operations. Simultaneous approach authorized. For inop ALS, increase LNAV Cat C/D visibility to 1% SM. 3000 direct APE VORTAC and hold. # RVR 1800 authorized with use of FD or AP or HUD to DA D-ATIS COLUMBUS APP CON COLUMBUS TOWER GND CON CLNC DEL **CPDLC** 124.6 125.95 371.975 132.7 257.8 126.3 121.9 348.6 4 NM HOT ²⁰²⁸∧ 9 FLANK 3300 APPLETON APE FLANK -♦ ρ 7 ∧¹²⁸⁰ **1**1129 **∧**¹¹⁹⁶ SILKN (FAF) (IF/IAF) 2.5 NM to **CCREW** FLANK RW10L 6000 1400 1 **1**029 RW10L HOLD 1113 3300 281 4 NM **∧**1748 Λ1116 2300 **∧**1094 101° (3.3) Λ 1166 **1748** 6 FLANK ٥ 3300 **ELEV** 815 D **TDZE** 815 101° to 1400 3000 APE **FLANK** RW10L 4 NM Holding Pattern **CCREW** SILKN 2.5 NM to 281° * LNAV only 6000 2300 RW10L 3300 101° *1.3 NM to TWR RW10L 1026 RW10I 2300 GP 3.00° *1660 TCH 50 3.3 NM 2 NM -1.2 NM-CATEGORY ח Α 1015/24 LPV DA# 200 (200-1/2) LNAV/ DA 1197/35 382 (400-%) VNAV LNAV MDA 1280/24 465 (500-1/2) 1280/50 465 (500-1) TDZ/CL Rwy 10R-28L 1520-2 1520-21/4 C CIRCLING 1340-1 525 (600-1) HIRL Rwys 10R-28L and 10L-28R 705 (800-2) 705 (800-21/4)