Amdt 12 12AUG21

FORT LAUDERDALE, FLORIDA AL-744 (FAA) 21280 LOC/DME I-UDL 8394 ILS or LOC RWY 28R Rwy Idg APP CRS 110.7 TDŹE 276° FORT LAUDERDALE/HOLLYWOOD INTL (FLL) Apt Elev 65 Chan 44 DME or RADAR required. RNP APCH - GPS from CRNVL MALSR MISSED APPROACH: Climb to 800 then climbing right turn to 4000 on FLL VOR/DME Simultaneous approach authorized. Inop table does not apply (Å5) R-305 to HUKUK INT/FLL 15 DME and hold, to S-ILS 28R. For inop ALS, increase S-LOC 28R Cats C and D visibility to 1 \(^3\)\(^4\) A continue climb-in-hold to 4000. MIAMI APP CON FORT LAUDERDALE TOWER GND CON CLNC DEL D-ATIS **CPDLC** 135.0 133.775 285.6 119.3 257.8 121.4 128.4 MISSED NSA FLL 25 M APCH FIX 113.9 DHP 3050 Chan 86 ·125° 2100 .P.305 Chan 91 HUKUK INT LOCALIZER 110.7 FLL [15) I-UDL ≝ ; Chan 44 ∧<sup>499±</sup> \*A.305. 4500 HOLD 4000 SNAPE ∧<sup>324</sup> I-UDL 7.5 RADAR 096% 250± 2000 276° 2769 096 FORT LAUDERDALE (6.3)114.4 FLL :=: (IF/IAF) 4000 to FUZYY Chan 91 **FUZYY** 096° (13.8) I-UDL 13.8) 4000 NoPT (IAF) RADAR 290° (9.2) Λ<sup>1049</sup> CRNVL 510<sub>^</sub> ALTERNATE MISSED APCH FIX Procedure NA for arrival on FLL VOR/DME airway radials 046 CW 121. FIFV 65 **TDZE TEYUK INT** VKZ 33.6 117.1 VKZ Chan 118 276° 6.1 NM 800 4000 VGSI and ILS glidepath not coincident from FAF 66 (VGSI Angle 3.00/TCH 69). HUKUK FUZ<u>YY</u> One Minute INT Holding Pattern FLL I-UDL 13.8 RADAR SNAPE R-305 I-UDL 7.5 TWR RADAR 194 = I-UDI 4500 2.8 2000 8000 X 150 I<u>-UD</u>L 4000 1.4 GS 3.00° 2000 TCH 49 -1.4 NM -- 4.7 NM -6.3 NM CATEGORY Α D 257/40 S-ILS 28R 250 (200-3/4) HIRL Rwy 10L-28R and 10R-28L S-LOC 28R 520/24 513 (500-1/2) 520/55 513 (500-1) FAF to MAP 6.1 NM 90 120 150 180 Knots 800-2 800-21/4 C CIRCLING 680-1 615 (700-1) Min:Sec | 6:06 | 4:04 3:03 2:26 2:02 735 (800-2) 735 (800-21/4) FORT LAUDERDALE/HOLLYWOOD INTL (FLL) FORT LAUDERDALE, FLORIDA

ILS or LOC RWY 28R

24 FEB 2022

2

27 JAN 2022

SE-3.