APP CRS

068°

Rwy Idg 10002

ROCKFORD APP CON

121.0 327.0

742

742

TDŹF

Aircraft not GPS equipped - RADAR required for procedure entry.

Requires specific OPSPEC, MSPEC, or LOA approval.

Apt Elev

LOC/DME I-UDY

109.55

Chan 32(Y)

RNP APCH - GPS

ATIS

127.6

₹2890...

MISSED APCH FIX -R-289-1090

JANESVILLE 114.3 JVL : ...

Chan 90

(IAF)

HENOR

Δ

ASR

ROCKFORD TOWER

118.1 290.375

۸¹⁵⁴²

ALSF-2

(Å) ₩

۸¹⁵⁴⁹

ILS RWY 7 (SA CAT I)

CLNC DEL

119.25

LOCALIZER 109.55

2600

TDZE 742

I-UDY

CHICAGO/ROCKFORD INTL(RFD)

MISSED APPROACH: Climb to 1700

∧1273

1147

VOR/DME and hold.

۸⁹⁵⁹

916

843

GND CON

121.9 290.375

360° and JVL VOR/DME R-165 to JVL

then climbing left turn to 3100 on heading

1700

CUDUP I-UDY (7.2)

2500

2500

В

SA CATEGORY I ILS - SPECIAL AIRCREW

& AIRCRAFT CERTIFICATION REQUIRED

RA 164/14 150 DA 892

6 NM

3100

hdg

JVL

JVL

R-165

M

REIL Rwys 19 and 25

TDZ/CL Rwys 1 and 7

HIRL Rwys 1-19 and 7-25

VGSI and ILS glidepath not coincident

068°

FOORD

I-UDY [13.2]

Α

(VGSI Angle 3.00/TCH 69).

4 NM

Holding Pattern

3000

GS 3.00°

TCH 60

CATEGORY

S-ILS 7

6000 ← 248°

5.3 NM