RNP APCH.

27 JAN 2022

ō

24 FEB 2022

WAAS Rwy ldg 6501 APP CRS CH **77720** TDŻE 22 097° Apt Elev 26 W10A

RNAV (GPS) RWY 10

MISSED APPROACH: Climb to 2000 direct RUYKI and hold.

TAMPA INTL (TPA)

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below 2°C or above 54°C D-ATIS DEP CLNC DEL TAMPA APP CON TAMPA TOWER **GND CON CPDLC** 126,45 128,475 118.5 307.175 119.5 269.4 121.7 269.4 133.6



ST PETERSBURG PIF Procedure NA for arrival

on PIE VORTAC airway radials 336 CW 067

RW 10 25 Ny 2700 **(**

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 42). 2000 **RUYKI** 4 NM Holding Pattern **POLVY** ZEXYY *LNAV only. 6000 1600 *1.3 NM to 2000 رو0 RW10 GP 3.00° TCH 57 1600 5.3 NM 3.5 NM **CATEGORY** В D LPV DA 272-1 250 (300-1) LNAV/ 436-1% 414 (500-1%) VNAV

LNAV MDA 480-1 458 (500-1) 480-13/8 458 (500-13/8) 680-13/4 980-3 C CIRCLING 560-1 534 (600-1)

19R 76 L 233 **(P)** 1L 097° to RW10 REIL Rwy 1R

D **TDZE** 22

ELEV

26

1667 ↑

654 (700-13/4) 954 (1000-3) TAMPA, FLORIDA

TAMPA INTL (TPA) RNAV (GPS) RWY 10

HIRL Rwys 1L-19R, 1R-19L, and 10-28

TDZ/CL Rwys 1L and 19L