ARR 123,775

LOCALIZER 110.9

I-RRA

SC-2,

27 JAN 2022

ਰ

24 FEB 2022

CPDLC

128.25

LOC/DME I-RRA APP CRS Rwy Idg 8373 110.9 TDŹF 523 3110 Apt Elev Chan 46

۸₈₀₄

135.5 125.2

ILS RWY 31R (SA CAT I & CAT II) DALLAS-FORT WORTH INTL (DFW)


121.65 121.8 EAST

Simultaneous approach authorized. DME required. SA Cat I: Requires specific OPSPEC, MSPEC, or LOA approval and use of HUD to DH. SA Cat II: Reduced lighting: Requires MALSR MISSED APPROACH: Climb to 1100 then climbing right turn to 3000 on heading 125° and TTT VOR/ $(\overline{A_5})$ specific OPSPEC, MSPEC, or LOA approval and use of DME R-084 to SOLDO/TTT 35.8 DME and hold. autoland or HUD to touchdown. **DFW TOWER** GND CON REGIONAL APP CON CLNC DEL

126.55 127.5 EAST

DEP 135.925 124.15 134.9 WEST 121.85 WEST ALTERNATE MISSED APCH FIX MISSED APCH FIX 116.2 CVE 116.2 CVE **SOLDO** RADAR REQUIRED Chan 109 SOLDO Chan 109 R-084 R-084 CVE 28.9 TTT [35.8) .·087°►/ R-087 <264°. 1<u>13.1</u> TTT R-087 113.1 TTT Chan 78 Chan 78

COWBOY



DALLAS-FORT WORTH, TEXAS Amdt 15 08NOV18

32°54′N-97°02′W

DALLAS-FORT WORTH INTL (DFW) ILS RWY 31R (SA CAT I & CAT II)