27 JAN 2022

ō

24 FEB

23L LOC I-LCK APP CRS Rwy Idg 12102 10913 TDŻE 743 110.1 232° 740 Apt Elev 744 ▲ Circling NA northwest of Rwy 5L-23R. When local altimeter setting not received, use John Glenn Columbus Intl altimeter setting: increase DA to 975 feet; increase all MDAs 40 feet and S-LOC 23L visibility


Cats C/D to RVR 5500 and Circling visibility Cat D to 2½ SM. Autopilot coupled approach NA below 1000 MSL.

ILS or LOC RWY 23L RICKENBACKER INTL (LCK)

MISSED APPROACH: Climb to 3000. then left turn direct XUB VOR and hold.

COLUMBUS APP CON RICK TOWER **ATIS** GND CON CLNC DEL 132.75 134.0 279.6 120.05 348.4 125.275 275.8 125.275 275.8

MALSR



TWR 852 + 6 69	VGSI and ILS (VGSI Angle 3	glidepath not coin.	cident 2372	232° - 232° - 2400
(A) MILES (A)		- 4.9 NA	١	
5/ 1	CATEGORY	Α	В	С
、 ダ 偽 TDZ/CL Rwy 5R REIL Rwy 23R	S-ILS 23L	940/24 200 (200-1/2)		
	S-LOC 23L	1220/24 480 (500-1/2)		1220/50
HIRL Rwys 5L-23R and 5R-23L	SIDESTEP			1220-11/2

SIDESTEP

RWY 23R

CIRCLING

COLUMBUS, OHIO Amdt 1B 09SEP21

Knots

Min:Sec

60

4:54 3:16 2:27

FAF to MAP 4.9 NM

90 120 150 180

> RICKENBACKER INTL (LCK) ILS or LOC RWY 23L

1220-11/2

477 (500-11/2)

1280-11/2

536 (600-11/2)

2900

480 (500-1)

1220-2

477 (500-2)

1400-2

656 (700-2)

GS 3.00° TCH 62 D

1240-1

1220-1 477 (500-1)

496 (500-1)