AL-5132 (FAA)

21112

RNAV (GPS) RWY 34L JACKSON-MEDGAR WILEY EVERS INTL (JAN)

WAAS 8500 Rwy Idg APP CRS CH 61301 TDŻE 329 339° Apt Elev 346 W34A RNP APCH

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -7°C or above 54°C.
Circling NA for Cat E southwest of Rwy 16R-34L. VDP and Baro-VNAV NA when using Hawkins ASR and increase all DA 19 feet and all MDA 20 feet, increase LNAV/VNAV all Cats visibility to 1½ SM and LNAV Cats C/D/E visibility to RVR 5000. For inop ALS, increase LNAV/VNAV Cat E visibility to 1% SM and LNAV Cat E visibility to 1% SM. For inop ALS when using Hawkins Fld altimeter setting, increase LPV Cat E visibility to RVR 4500, LNAV/VNAV Cat E visibility to 1% SM, and LNAV Cat E visibility to 1% SM. Inop table does not apply to LPV. Rwy 34L helicopter

MALSR MISSED APPROACH: Climb to 3000 direct MOPKE and hold.

٥,

7 NM

Holding Pattern

GP 3.00°


TCH 58

Е

1040-21/2

694 (700-21/2)

visibility reduction below RVR 4000 NA JACKSON APP CON★ JACKSON TOWER* GND CON UNICOM 120.7 0* 122.95 123.9 317.7 121.05 120.9 (CTAF) **(1)** 352.0 121.7 348.6 MISSED APCH FIX Λ 936 Λ 644 Λ 597 7 NM -RW34L MOPKE 1,639 ₅₈₈∧ 517 CEKB 2409 (FAF) FAVIN 2 NM to to 4WDABEY RW34L 24 FEB 3500 FAVIN SC-4, 27 JAN 2022 FAVIN 3000 FAVIH (IF/IAF) **FAVIN** NM to ELEV 346 **TDZE 329**



JACKSON, MISSISSIPPI Amdt 3C 22APR21

JACKSON-MEDGAR WILEY EVERS INTL (JAN)

32°19′N-90°05′W