6607 RNAV (RNP) Y RWY 2 Rwy Idg APP CRS TD7F 161 023° RICHMOND INTL (RIC) Apt Elev 168 RNP AR APCH MISSED APPROACH: MALSR Tor uncompensated Baro-VNAV systems, procedure NA below -11°C (13°F) or above Climb to 2100 on track 54°C (130°F). Rwy 2 helicopter visibility reduction below 3/4 SM NA. For inop ALS (Å5) 023° to IMASE and hold. increase RNP 0.11 all Cats visibility to 1 SM and RNP 0.3 all Cats visibility to 11/4 SM POTOMAC APP CON **GND CON** ATIS RICHMOND TOWER CLNC DEL 126.4 282.375 (001° 185°) 121.1 257.8 121.9 348.6 119.15 263.025 127.55 348.6 126.75 307.2 (186°-360° MISSED APCH FIX ¹⁰⁵⁷Λ (IF) ۸⁶⁵⁴ **BEKKY** 4000 1587 ∧(RF REQD 349 (IAF) DUCXS 1002 4000 (RF REQD) **1** 270 (IF) ACIL 3000 EÉMIL 210K 1300 1140 (FAF) 3000 (3.8)19.1) **FISSR** (RF REQD) (IF) 1300 **EMWHY** (5.7)2300 2600 114° (3.1) 210K 1300 248° (3) 023° (3) COVSO LJAAY 210K 210K (IF) CASEE RW02 25 2000 2600 **ELEV** 168 D **TDZE** 161 **(** TWR 343 See planview for multiple IF locations. **IMASE** 2100 FISSR 1300 tr 0239 1300 023° **RW02** GP 3.00° TCH 50 3.4 NM 023° to CATEGORY D RW02 345 (400-3/4) RNP 0.11 DA 506-3/4 RNP 0.30 DA 595-1 434 (500-1) TDZ/CL Rwy 34 HIRL Rwys 2-20 and 16-34 **AUTHORIZATION REQUIRED** REIL Rwy 20

RICHMOND, VIRGINIA Orig-B 19JUL18

27 JAN 2022

ō 24 FEB

> RICHMOND INTL (RIC) RNAV (RNP) Y RWY 2