8373 Rwy Idg APP CRS TDŹE 523 311° Apt Elev 607

27 JAN 2022

ō 24 FEB

RNAV (RNP) Z RWY 31R DALLAS-FORT WORTH INTL (DFW)

For uncompensated Baro-VNAV systems, procedure NA below -4°C (25°F) or above 54°C (130°F). For inop MALSR, increase RNP 0.14 all Cats visibility to RVR 5100, RNP 0.23 all Cats visibility to 1% mile, RNP 0.30 all Cats visibility to 1% mile. Simultaneous approach authorized with Rwy 31L. GPS Required. Use of FD or AP providing RNAV track guidance required during simultaneous operations.



MISSED APPROACH: Climb to 1100 then climbing right turn to 3000 direct SOLDO and hold.

