LOC/DME I-BFI | APP CRS | Rwy Idg | 110.9 | 135° | TDZE | Apt Elev | 22

## ILS or LOC RWY 14R

## BOEING FLD/KING COUNTY INTL (BFI)

▼ Circling NA for C and D northeast of Rwy 14L-32R. For inop ALS,

▲ increase S-LOC 14R visibility Cat A/B to RVR 5500, increase Cat
C/D visibility to 1% SM. DME and RADAR required. Rwy 14R
helicopter visibility below ¾ SM NA. Circling Rwy 32R NA at night.
S-ILS 14R # minimums NA when VGSI inop.



MISSED APPROACH: Climb on I-BFI SE course to cross OCEZE/I-BFI 3.9 DME/RADAR at or below 1500, then climb to 6400 on I-BFI SE course and SEA R-104 to BLAKO INT/SEA 11.8 DME and hold, continue climb-in-hold to 6400.

5-ILS 14K # minimums NA when VGSI Inop.			hold, continue climb-in-hold to 6400.		
ATIS <b>127.75</b>	SEATTLE APP CON <b>119.2 284.7</b>	BOEING TO 120.6 2		GND CON <b>121.9</b>	CLNC DEL <b>132.4</b>
	(IF/L ISO I-BFI SEA [ RAD	GE 9 A desc 13.2 may be	ent to at or bel required whe y missed appro	ow 1500 n executing	3400 6400 2200 3
	TOGAE  -BFI   6.6  RADAR   426± A   328	Λ 532	∧635 ∧400 ∧473 ∧662	Λ(610± Δ(1745	
l '	LOCALIZER 110.9 I-BFI 10.9 Chan 46	<u>∧</u> 646 ∰	589	∧ 216 ∧ 657±	54 <b>∧</b> 3149
ELEV 22 D			576 A OCE  -BFI   RAD 639 150	3.9) AR 00	MISSED APCH FIX
from FAF	VGSI and (VGSI Ar	d ILS glidepath not on the state of the stat	<u> </u>	I-BFI   3.9	SEA R-104 A  Use I-BFI DME when on
TWR →	2200 -	ng Pattern  —315°  135° —	1-BFI RAD 1350	PAR I-BFI 4.7 00 RADAR *I	the localizer course.  *LOC only 3.4    I-BFI   1.7
1	GS 3.00 TCH 39 CATEGO	-	600 -2.4 NM	*1080 1.9 NM1.4 NM B C	-1.6 NM - D
S-ILS 14R# 308/40 290 (300-34)					
MIRL Rwy 14L-32R HIRL Rwy 14R-32L	S-LOC 1	740.1	10 562 (600 880	- <sub>34</sub> ) 580- 0-1½ 960-2	

SEATTLE, WASHINGTON Amdt 31B 05NOV20

REIL Rwys 14L, 32L and 32R

NW-1, 27 JAN 2022

ਰ

24 FEB 2022

738 (800-1) 47°32′N-122°18′W 858 (900-11/4) | 938 (1000-21/4) | 938 (1000-3) BOEING FLD/KING COUNTY INTL (BFI)