

Certificate of Inspection

SITE DETAILS	
Site Name:	Brookline Building
Site Address:	20 Egmont Street, Sherwood QLD 4075

SYSTEM INFORMATION	
System Type	Industrial Rope Access & Fall Arrest
Inspected To	ISO 22846 Industrial Rope Access Systems AS/NZS 1891.4:2025 Industrial Fall Arrest Systems & Device
System Purpose	Rope Access Anchorage System for Window Cleaning

CERTIFIED COMPONENTS		FAILED OR EXCLUDED COMPONENTS	
The following components have been certified:		The following components have failed or been excluded from this inspection:	
22 x SafetyLink FrogLine – Fall Arrest Anchor – 15k=kN 92 x Sayfa AP141 – Surface Mount Abseil Anchor – 15kN		Any other items not mentioned in this report	
Date of Inspection	29/04/2026	Certificate Expiry	29/04/2027

COMMENTS
All components found to be compliant during this inspection have been fitted with updated certification tags. Failed components have been tagged out of service. For further information on individual components, refer to system inspection report. Rope Access Technicians Pty Ltd takes no responsibility for any part of the system that is not listed in the inspection report. This inspection is not a comprehensive height safety audit and should not be relied upon as an exhaustive record of all possible height safety related risks or hazards that may exist or potential improvements that can be made. To remain compliant with Australian Standards, anchor points must be inspected by a height safety equipment inspector at intervals no greater than 12 months. Inspections must be documented. Installation and inspection documentation should be made readily available to all users of the system. Certification of the system does not absolve any persons of their obligations under the WH&S Act, relevant Regulations, Industry Codes or Australian Standards. This is not an operator's manual and as such is not providing details on the correct and safe use of the system.

AUTHORISED BY	SIGNATURE	DATE
Peter Knapp		29/04/2026

2026 Inspection Report

Brookline – Sherwood QLD

Prepared By: Peter Knapp

Date: 29/04/2026

Document ID: IR 26033

Table of Contents

Certificate of Inspection	1
DISCLAIMER	4
Report Information	5
Inspection & Test Methodology	6
Inspection & Test Results	7
Site Plan	11

DISCLAIMER

Rope Access Technicians believes the information contained within this report to be correct at the time of issue.

Rope Access Technicians was commissioned to undertake an inspection of height safety components at this site. This is not a comprehensive height safety audit and should not be relied upon as an exhaustive record of all possible height safety related risks or hazards that may exist or potential improvements that can be made.

Upon completion of this inspection, a certificate detailing the results shall be provided to the client. This certificate should be made readily available to users of the system.

Certification of the system does not absolve any persons of their obligations under the WH&S Act, relevant Regulations, Industry Codes or Australian Standards.

This is not an operator's manual and as such is not providing details on the correct and safe use of the system.

Report Information

Client:	The Body Corporate for Brookline CTS 39899
Site Name:	Brookline Building @ Parklands at Sherwood
Address:	20 Egmont Street, Sherwood QLD 4075
Site Contact:	Kurt Zhao – 0438 166 892
System Installed:	22 x SafetyLink FrogLine – Fall Arrest Anchor – 15kN 92 x Sayfa AP141 – Surface Mount Abseil Anchor – 15kN
Component Manufacturers:	Sayfa, Safeylink
Installed By:	Safe @ Heights
Installation Date:	04/03/2016
System Type:	Rope Access & Fall Arrest
System Location:	Rooftop
System Rating:	Fall Arrest Components = 15 kN (1 anchor per person) Rope Access Components = 15 kN (2 anchors per person)
Inspection Completed by:	Zeb Nicklin
Inspection Date:	29/04/2026
System ID Sign:	No
Anchor Plan:	Yes in this report
User Manual Provided:	Pending Review
Test Equipment Used:	Visual
Test Equipment Calibration Date:	N/A
Test Exclusions:	Any other items not covered by this report
Report Written by:	Peter Knapp

Inspection & Test Methodology

Anchor Points

In accordance with Australian Standard 1891.4:2009 – Industrial fall-arrest systems and devices and AS4488.2:1997 – Industrial rope access systems, permanently installed anchor points are to be inspected at intervals not exceeding 12 months. The anchorages are visually inspected for signs of deterioration, which might make them unserviceable, together with any other requirements contained in manufacturers' instructions. The parent structure is also visually inspected for modifications or deterioration which might lead to loss of anchor strength. Drilled-in, glued-in and friction anchors are proof loaded by application of an axial pull-out force of 50% of the anchor's design load (this equates to 6kN for rope access, 7.5kN for fall-arrest).

Horizontal and Vertical Life Lines and Rails

In accordance with Australian Standard 1891.4:2009 – Industrial fall-arrest systems and devices, life lines of steel construction and rails are to be inspected by a height safety equipment inspector at intervals as recommendation by the manufacturer to a maximum of five-yearly. In the absence of such a recommendation, static lines are to be inspected on an annual basis. The inspection is carried out in accordance with the manufacturer's instructions. Line anchorage points and rail support anchorages are inspected as per the methodology for anchor points above. The parent structure is inspected for any modification or deterioration which might lead to a loss of anchorage strength. Cables terminations, line tensioners, fixings and other system components are inspected in accordance with AS1891.4 clause 9.3.5.

Important! Any system which has not been certified in over 12 months cannot be used. All inspections are to be documented. Upon completion of the annual testing regime, a certificate detailing the results of the inspection should be supplied to building management. This certificate and any installation documentation should be made readily available to users of the system.

Inspection & Test Results

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
1	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
2	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
3	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
4	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
5	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
6	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
7	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
8	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
9	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
10	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
11	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
12	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
13	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
14	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
15	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
16	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
17	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
18	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
19	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
20	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
21	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
22	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
23	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
24	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
25	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
26	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
27	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
28	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
29	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
30	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
31	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
32	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
33	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
34	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
35	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
36	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
37	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
38	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
39	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
40	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
41	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
42	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
43	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
44	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
45	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
46	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
47	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
48	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
49	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
50	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
51	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
52	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
53	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
54	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
55	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
56	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
57	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
58	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
59	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
60	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
61	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
62	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
63	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
64	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
65	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
66	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
67	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
68	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
69	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
70	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
71	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
72	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
73	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
74	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
75	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
76	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
77	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
78	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
79	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
80	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
81	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
82	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
83	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
84	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
85	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
86	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
87	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
88	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
89	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
90	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
91	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
92	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
93	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
94	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
95	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
96	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
97	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
98	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
99	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
100	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
101	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
102	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
103	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
104	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
105	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
106	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
107	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
108	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
109	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
110	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
111	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
112	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
113	FA	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
114	MULTI	AP - SM	Rooftop	Good	Good	Visual	Visual	PASS
COMMENTS:			All anchors have been tested in accordance with and ISO 22846 & ASNZS 1891 and have passed unless listed otherwise above. All tested anchors have been tagged (unless listed otherwise above) and their locations clearly identified on the site plan section of this document. All other anchors not listed in these test results are excluded from this inspection. Site signage updated if installed.					

INSPECTION & TEST LEGEND		
ITEM USE	FA – Fall Arrest / RA – Rope Access / DIV – Diversion / AID – Aid Climbing Point / MULTI – Fall Arrest & Rope Access / OTHER – Other	
ITEM TYPE	ITEM TYPE	AP – Anchor Point / HL – Horizontal Lifeline / VL – Vertical Lifeline / L – Ladder / LB – Ladder Bracket / ST – Strop / HAR – Harness / SRL – Self Retracting Lanyard / LAN – Lanyard / ROP – Rope / SD – Safety Device / CAR – Carabiner
	FIXING METHOD (Anchors Only)	C – Chemically Set / FR – Friction Anchor / TB – Through Bolt / PA – Purlin Anchor SM – Surface Mount Anchor / TR – Truss Mount Anchor

Site Plan

