1/11/2024 Issue syncing sales data from ERP into robotics supply chain dashboard. 2/9/2025 Battery drain accelerating on self-navigating picker botsclient requests hardware review, 2/9/2024 Customer account flagged as inactive during quarterly syncontract still in force until Q4. 6/15/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 12/11/2024 Medium Cancelled 3/11/2025 Pick path optimization feature stuck in recalculating looplikery route matrix bug. 3/11/2024 Custom firmware deployment not stickingdevice reverts to factory version after reboot. 8/20/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 3/9/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 3/9/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 3/13/2025 Service report PDF not attaching to customer CRM recordautomation flow broken. 1/12/2024 Issue syncing sales data from ERP into robotics supply chain dashboard. 1/13/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch. 1/15/2025 Amature alignment reset required after shippingrequesting field calibration. 4/9/2025 Field PDF on attaching duplicate status updatescausing client-side UI clutter. 5/16/2025 Amature alignment reset required after shippingrequesting field calibration. 4/9/2025 High Closed 2/10/2025 Unesse expiration alerts not appearing for client adminimonitoring system inactive. 6/16/2024 Medium Closed Resolved 2/10/2025 Unesse expiration alerts not appearing for client adminimonitoring system inactive. 6/16/2024 Medium Closed - Resolved 1/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 5/1/2024 Edeback toop delay causing robotic pallectize to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic pallectize to miss timing sync with conveyor belt. 6/16/2024 Medium Closed - Resolved 1/16/2025 Nettinu round page resolved ask	submission_date issue_description	resolution_date priority_level	ticket_status
6/9/2024 Customer account flagged as inactive during quarterly synccontract still in force until Q4. 12/6/2024 Delivery tracking API pushing duplicate status updatescausing client-side U clutter. 12/11/2025 Pick path optimization feature stuck in recalculating looplikely route matrix bug. 8/11/2024 Custom firmware deployment not stickingdevice reverts to factory version after reboot. 8/20/2024 High In Progress 12/23/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 13/2/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 11/20/2025 Urgent On Hold 11/17/2024 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken. 11/20/2025 Service report PDF not attaching to customer CRM recordautomation flow broken. 11/20/2025 Averice report PDF not attaching to customer CRM recordautomation flow broken. 11/23/2024 View PS234 Missing firmware version S. J for VRZ Series actuatorrequires urgent patch. 12/23/2024 High Open 4/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 4/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 4/5/2025 Armature alignment reset required after shippingrequesting field calibration. 1/11/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 5/18/2024 Delivery tracking API pushing duplicate status undatescausing client-side U clutter. 5/18/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 1/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 1/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 5/17/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/17/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/17/2024 Night shift override not deactivating during scheduled switchlogic con	11/11/2024 Issue syncing sales data from ERP into robotics supply chain dashboard.	11/19/2024 Medium	Closed - Resolved
12/6/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 3/11/2025 Pick path optimization feature stuck in recalculating looplikely route matrix bug. 3/11/2024 Custom firmware deployment not sticking device reverts to factory version after reboot. 3/20204 Midbile control app crashing after recent OS updatecompatibility fix required. 3/9/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 3/19/2025 Use Closed - Resolved 1/13/2025 Use Closed - Resolved 1/13/2025 Service report PDF not attaching to customer CRM recordautomation flow broken. 11/20/2024 High Closed - Resolved 1/13/2025 Service report PDF not attaching to customer CRM recordautomation flow broken. 12/13/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch. 12/13/2024 Sisue syncing sales data from ERP into robotics supply chain dashboard. 1/9/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 4/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 1/11/2025 High Closed - Resolved 2/10/2025 Lighen y tracking API pushing duplicate status updatescausing client-side UI clutter. 5/12/2025 High Closed - Resolved 2/10/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 6/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 1/13/2024 Eventual Closed Control app crashing after recent OS updatecompatibility fix required. 1/13/2024 Feedback loop delay causing robotic palletter to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletter to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletter to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletter to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletter to miss timing sync with conveyor belt. 5/1/	2/9/2025 Battery drain accelerating on self-navigating picker botsclient requests hardware review.	2/14/2025 High	On Hold
3/11/2025 Pick path optimization feature stuck in recalculating looplikely route matrix bug. 8/11/2024 Custom firmware deployment not stickingdevice reverts to factory version after reboot. 8/20/2024 High In Progress 12/23/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 3/9/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 3/9/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 11/18/2025 Service report PDF not attaching to customer CRM recordatuomation flow broken. 11/20/2025 Medium Closed - Resolved 11/18/2025 Service report PDF not attaching to customer CRM recordatuomation flow broken. 11/20/2025 Medium Closed - Resolved 12/13/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch. 11/9/2025 Medium Open 11/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 11/9/2025 Medium Open 11/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 11/12/2025 High Open 11/5/2025 Armature alignment reset required after shippingrequesting field calibration. 11/12/2025 Lilegan expiration alerts not appearing for client adminional training system inactive. 11/12/2025 Lilegan expiration alerts not appearing for client adminional training system inactive. 11/12/2025 Lilegan expiration alerts not appearing for client adminional training system inactive. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/16/2024 Vigent Closed - Reso	6/9/2024 Customer account flagged as inactive during quarterly synccontract still in force until Q4.	6/15/2024 Urgent	Closed
8/11/2024 Custom firmware deployment not stickingdevice reverts to factory version after reboot. 1/2/2025 tow Closed - Resolved 12/23/2025 tow Closed - Resolved 3/9/2025 Temperature-controlled arm not holding cold-pack products steadilized trained are not products steadilized trained and steadilized are not products steadilized trained are not products steadilized trained are not products steadilized trained and steadilized are not products steadilized trained are not products are not pro	12/6/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter.	12/11/2024 Medium	Cancelled
1/2/20/204 Mobile control app crashing after recent OS updatecompatibility fix required. 3/9/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 3/19/2025 Urgent On Hold 1/11/2024 Heat map of robotic traffic not loading for West Coast territory/sualization component broken. 1/12/2025 Service report PDF not attaching for West Coast territory/sualization component broken. 1/20/2025 Medium Closed - Resolved 1/2/31/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch. 1/2/31/2024 Isign Grimware version 5.3 for XYZ Series actuatorrequires urgent patch. 1/9/2025 Medium Open 4/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 4/9/2025 High Open 1/5/2025 Armature alignment reset required after shippingrequesting field calibration. 1/1/2025 High Open 1/5/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 5/26/2024 Unventory report mislabeling robotics model numbersSkU logic misfire. 6/9/2024 Inventory report mislabeling robotics model numbersSkU logic misfire. 7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 1/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic model familyrollback request submitted. 5/1/2024 Feedback loop delay causing robotic model familyrollback request submitted. 5/1/2024 Feedback loop delay causing robotic model familyrollback request submitted. 5/1/2024 Feedback loop delay causing robotic model familyrollback request submitted. 5/1/2024 Fight in Progress 1/2/2025 Data not syncing across international locationstimezone setting	3/11/2025 Pick path optimization feature stuck in recalculating looplikely route matrix bug.	3/12/2025 Medium	Open
3/9/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 11/17/2024 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken. 11/20/2025 Service report PDF not attaching to customer CRM recordautomation flow broken. 12/13/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch. 12/13/2024 High Cancelled 12/31/2024 Issue syncing sales data from ERP into robotics supply chain dashboard. 19/2025 Medium Open 4/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 1/11/2025 High Open 1/5/2025 Armature alignment reset required after shipping requesting field calibration. 1/11/2025 High Closed 5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 5/26/2024 Urgent Closed - Resolved 2/10/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 2/11/2/2025 High On Hold 6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 6/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/16/2024 Gustomer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 11/16/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 4/2/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 4/6/2025 High In Progress 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 4/18/2024 API returning mull values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 1/	8/11/2024 Custom firmware deployment not stickingdevice reverts to factory version after reboot.	8/20/2024 High	In Progress
11/17/2024 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken. 11/20/2025 Medium 12/31/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch. 12/31/2024 Issue syncing sales data from ERP into robotics supply chain dashboard. 11/9/2025 Medium Open 4/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 11/5/2025 Armature alignment reset required after shippingrequesting field calibration. 11/5/2025 Armature alignment reset required after shippingrequesting field calibration. 11/5/2025 Armature alignment reset required after shippingrequesting field calibration. 11/5/2025 Polity tracking API pushing duplicate status updatescausing client-side UI clutter. 5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 2/10/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 2/11/2/2025 High On Hold 6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 6/16/2024 Medium Closed 7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 7/31/2024 High Closed - Resolved 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 15/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Eatest patch rolled out to wrong robot model familyrollback request submitted. 9/1/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 16/1/2024 Might shift overturing null values for order tracking endpointbackend request timing out. 5/1/2024 High On Hold 10/6/2024 Night shift override mode triggering false alarmsUI miscommunication suspected. 7/12/2024 High On Hold 11/6/2025 Suction cup gr	12/23/2024 Mobile control app crashing after recent OS updatecompatibility fix required.	1/2/2025 Low	Closed - Resolved
1/18/2025 Service report PDF not attaching to customer CRM recordautomation flow broken. 1/2/13/2024 Missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch. 12/31/2024 Issue syncing sales data from ERP into robotics supply chain dashboard. 4/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 4/5/2025 Armature alignment reset required after shipping requesting field calibration. 1/51/2025 Armature alignment reset required after shipping requesting field calibration. 1/51/2025 Armature alignment reset required after shipping requesting field calibration. 1/11/2025 High Closed 5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 2/10/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 1/1/2024 Low Cancelled 1/1/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 1/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 4/2/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 4/6/2025 High In Progress 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 1/4/2025 Medium Open 1/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 1/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 7/12/2024 Medium In Progress 1/16/2025 Suction cup gripper losing pressure after	3/9/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected.	3/19/2025 Urgent	On Hold
12/13/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch. 12/31/2024 Issue syncing sales data from ERP into robotics supply chain dashboard. 4/9/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 1/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 1/5/2025 High Open 1/5/2025 Armature alignment reset required after shippingrequesting field calibration. 1/11/2025 High Closed - Resolved 5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 5/26/2024 Urgent Closed - Resolved 2/10/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 6/16/2024 Medium Closed 6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/20/2024 Low Cancelled 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Hedium Open 4/2/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 4/6/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 4/6/2025 High In Progress 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/1/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 10/6/2024 Picking robot skipping assign	11/17/2024 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken.	11/20/2024 Low	Closed
12/31/2024 Issue syncing sales data from ERP into robotics supply chain dashboard. 1/9/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 4/9/2025 High Open 1/5/2025 Armature alignment reset required after shippingrequesting field calibration. 5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 5/26/2024 Urgent 2/10/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 6/16/2024 Medium Closed 7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/16/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/7/2024 Medium Open 4/2/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 9/1/2024 Low Cancelled 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 4/20/2025 Medium Open 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 1/2/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/2/9/2024 Technician override mode triggering false alarmsUl miscommunication suspected. 1/2/9/2024 Urgent Closed - Resolved 1/2/9/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed 2/24/2025 Medium Open 1/2/6	1/18/2025 Service report PDF not attaching to customer CRM recordautomation flow broken.	1/20/2025 Medium	Closed - Resolved
4/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration. 4/9/2025 High Closed 1/5/2025 Armature alignment reset required after shippingrequesting field calibration. 5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 5/18/2024 License expiration alerts not appearing for client adminmonitoring system inactive. 5/19/2024 liventory report mislabeling robotics model numbersSKU logic misfire. 6/16/2024 Medium Closed 7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 11/16/2024 High Closed - Resolved 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 4/2/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 4/28/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 9/1/2024 Low Cancelled 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 4/20/2025 Medium Dio/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent 10/2024 Vigent Closed - Resolved 11/2/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 11/29/2024 Urgent 12/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/28/2025 Livense reports robotic forklift overshooting dock	12/13/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch.	12/23/2024 High	Cancelled
1/5/2025 Armature alignment reset required after shippingrequesting field calibration. 1/11/2025 High Closed 5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 5/26/2024 Urgent Closed - Resolved 2/10/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 6/9/2024 Lostomer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 7/31/2024 High Closed - Resolved 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/20/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 9/1/2024 Low Cancelled 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 4/20/2025 Medium Open 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 7/12/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 11/6/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed - Resolved 1/26/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 12/16/2024 High Closed - Resolved 12/27/2024 Customer reports robotic forklift overshooting dock alignmentcamera offs	12/31/2024 Issue syncing sales data from ERP into robotics supply chain dashboard.	1/9/2025 Medium	Open
5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter. 2/10/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 2/12/2025 High On Hold 6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 5/12/204 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/12/204 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/12/205 Battery health metrics not populating in regional dashboardtelemetry stream missing. 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 9/1/2024 Low Cancelled 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 4/20/2025 Medium Open 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 7/12/2024 Medium In Progress 12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/29/2024 Urgent Closed - Resolved 1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 1/2/16/2024 High Closed - Resolved 1/2/16/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 1/2/16/2024 High In Progress	4/5/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration.	4/9/2025 High	Open
2/10/2025 License expiration alerts not appearing for client adminmonitoring system inactive. 6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 6/16/2024 Medium Closed 7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 11/20/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2024 Heedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/7/2024 Medium Open 4/2/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 7/9/2024 Technician override mode triggering false alarmsUl miscommunication suspected. 7/12/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/26/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed - Resolved 1/27/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 1/2/16/2024 High Closed - Resolved 2/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 1/2/10/204 Label printer on packing bot jamming intermittentlyhardware service request opened.	1/5/2025 Armature alignment reset required after shipping requesting field calibration.	1/11/2025 High	Closed
6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire. 6/16/2024 Medium Closed 7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 4/28/2025 Latest patch rolled out to wrong robot model familyrollback request submitted. 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 4/20/2025 Medium Open 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 7/9/2024 Technician override mode triggering false alarmsUl miscommunication suspected. 1/2/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/2/3/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/2/2025 Low Closed 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 1/2/6/2024 High Closed - Resolved 1/2/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 1/2/6/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	5/18/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter.	5/26/2024 Urgent	Closed - Resolved
7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing. 7/31/2024 High Closed - Resolved 11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 4/20/2025 Medium Open 10/6/2024 Technician override not deactivating during scheduled switchlogic conflict in script. 7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 1/24/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/26/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed - Resolved 1/25/2025 Ucg Ucg Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 1/27/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 1/216/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 High In Progress	2/10/2025 License expiration alerts not appearing for client adminmonitoring system inactive.	2/12/2025 High	On Hold
11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required. 5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 5/1/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 1/2/1/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 1/2/6/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	6/9/2024 Inventory report mislabeling robotics model numbersSKU logic misfire.	6/16/2024 Medium	Closed
5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt. 4/2/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 7/9/2024 Technician override mode triggering false alarmsUl miscommunication suspected. 12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 11/6/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 12/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 12/16/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 12/30/2024 High In Progress	7/21/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing.	7/31/2024 High	Closed - Resolved
4/2/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing. 4/6/2025 High In Progress 8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 12/9/2024 Urgent Closed - Resolved 1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 12/1/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 12/16/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 12/30/2024 High In Progress	11/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required.	11/20/2024 Low	Cancelled
8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted. 9/1/2024 Low Cancelled 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 5/7/2024 High On Hold 4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 4/20/2025 Medium Open 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent 7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 7/12/2024 Medium In Progress 12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 2/24/2025 Medium Cancelled 12/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 12/16/2024 High Closed - Resolved 2/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	5/1/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt.	5/7/2024 Medium	Open
4/28/2024 API returning null values for order tracking endpointbackend request timing out. 4/28/2024 API returning null values for order tracking endpointbackend request timing out. 4/20/2025 Medium Open 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 1/27/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 1/2/6/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 1/2/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 1/2/30/2024 High In Progress	4/2/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing.	4/6/2025 High	In Progress
4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed. 4/20/2025 Medium Open 10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 10/10/2024 Urgent Closed - Resolved 7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 12/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 12/16/2024 High Closed - Resolved 2/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 12/30/2024 High In Progress	8/25/2024 Latest patch rolled out to wrong robot model familyrollback request submitted.	9/1/2024 Low	Cancelled
10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script. 7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 7/12/2024 Medium In Progress 12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 1/27/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 2/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 12/30/2024 High In Progress	4/28/2024 API returning null values for order tracking endpointbackend request timing out.	5/7/2024 High	On Hold
7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected. 12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 1/2/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 1/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 1/2/1/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 1/2/30/2024 High In Progress	4/14/2025 Data not syncing across international locationstimezone setting discrepancies confirmed.	4/20/2025 Medium	Open
12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted. 1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 12/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 12/16/2024 High Closed - Resolved 2/24/2025 Medium Closed - Resolved 2/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 12/30/2024 High In Progress	10/6/2024 Night shift override not deactivating during scheduled switchlogic conflict in script.	10/10/2024 Urgent	Closed - Resolved
1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity. 1/25/2025 Low Closed 2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 2/24/2025 Medium Cancelled 12/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 2/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 12/30/2024 High In Progress	7/9/2024 Technician override mode triggering false alarmsUI miscommunication suspected.	7/12/2024 Medium	In Progress
2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected. 12/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 2/24/2025 Medium Cancelled 12/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 12/16/2024 High Closed - Resolved 2/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 12/30/2024 High In Progress	12/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted.	12/9/2024 Urgent	Closed - Resolved
12/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected. 12/16/2024 High Closed - Resolved 2/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 12/30/2024 High In Progress	1/16/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	1/25/2025 Low	Closed
2/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions. 3/4/2025 Medium Open 12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 12/30/2024 High In Progress	2/23/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected.	2/24/2025 Medium	Cancelled
12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened. 12/30/2024 High In Progress	12/7/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected.	12/16/2024 High	Closed - Resolved
	2/26/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions.	3/4/2025 Medium	Open
1/28/2025 Temperature sensor in robotic soldering unit reading above safe operating range. 2/4/2025 High On Hold	12/21/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	12/30/2024 High	In Progress
	1/28/2025 Temperature sensor in robotic soldering unit reading above safe operating range.	2/4/2025 High	On Hold

10/15/2024 Customer unable to submit service ticket via mobile portalUI issue on latest Android version.	10/23/2024 Medium	Closed
8/3/2024 LED status indicator stuck in red despite system running normallyvisual false positive?	8/4/2024 Urgent	Closed - Resolved
5/18/2024 Customer states predictive maintenance alert was missedpossible alert suppression rule.	5/20/2024 Medium	Closed - Resolved
6/12/2024 AI co-pilot interface displaying outdated warehouse inventory despite live API integration.	6/21/2024 High	In Progress
12/25/2024 System audit flagging unauthorized access attempt on robotics control API.	1/3/2025 Low	Closed - Resolved
1/1/2025 Idle time tracking for warehouse units not logging correctlytelemetry data gap.	1/4/2025 High	Closed
9/28/2024 Diagnostic tool unable to communicate with legacy hardwareadapter may be required.	9/29/2024 Low	Cancelled
5/4/2024 Automated welding arm intermittently halts during high-heat cyclessuspected sensor calibration drift.	5/13/2024 Medium	On Hold
8/29/2024 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken.	8/30/2024 Urgent	Open
6/16/2024 Battery drain accelerating on self-navigating picker botsclient requests hardware review.	6/18/2024 High	Closed - Resolved
4/23/2024 Unexpected stop condition triggered during pallet rewrap routineinvestigating fault codes.	4/30/2024 Medium	Cancelled
11/12/2024 Repeated '404 device not found' error on support dashboardbelieved to be ID mismatch.	11/17/2024 High	Open
11/14/2024 Return unit not accepting scanned QR codesoptical reader needs recalibration.	11/14/2024 Urgent	In Progress
9/7/2024 Navigation system freezing mid-shiftpacket loss observed in Wi-Fi logs.	9/7/2024 Low	Closed - Resolved
9/19/2024 Unable to reset robotic arm to home positionreset protocol fails at step 3.	9/27/2024 Medium	On Hold
12/9/2024 Customer service chatbot incorrectly routing requests about robotic arms to finance.	12/19/2024 Medium	Closed
2/13/2025 Customer account flagged as inactive during quarterly synccontract still in force until Q4.	2/19/2025 High	Closed - Resolved
8/31/2024 Customer reports excessive heat on robotics control panelcooling fan test requested.	9/1/2024 High	Closed - Resolved
7/27/2024 Pick path optimization feature stuck in recalculating looplikely route matrix bug.	7/28/2024 Low	Open
2/12/2025 Inconsistent barcode scanning during inbound sortationrequesting diagnostic logs.	2/18/2025 High	Closed
6/21/2024 Issue syncing sales data from ERP into robotics supply chain dashboard.	6/26/2024 Urgent	In Progress
3/31/2025 Billing dashboard showing duplicate line items for SLA renewalneeds manual reconciliation.	4/8/2025 Medium	Cancelled
12/1/2024 Custom firmware deployment not stickingdevice reverts to factory version after reboot.	12/6/2024 Medium	On Hold
11/3/2024 Support agent unable to replicate power cycling bug reported on new Roboweld Plus series.	11/6/2024 Low	On Hold
6/11/2024 Service report PDF not attaching to customer CRM recordautomation flow broken.	6/18/2024 High	Open
2/17/2025 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch.	2/22/2025 Medium	Closed - Resolved
9/20/2024 Support team reports double charge on robotic part restockSLA breach inquiry pending.	9/29/2024 Urgent	Closed - Resolved
10/1/2024 Discrepancy between scanned and delivered SKUspotential robotic misclassification event.	10/8/2024 High	Closed
7/6/2024 Product loader mistiming drop-off with downstream conveyorsync pulse missing.	7/9/2024 Medium	In Progress
11/21/2024 Voice command module failing to recognize commands with headset mic input.	12/1/2024 Low	Cancelled
4/29/2024 Downtime incorrectly logged as resolved in dashboardresolution timestamp error.	4/30/2024 High	Cancelled
12/14/2024 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	12/21/2024 Medium	Open
2/8/2025 Scheduled maintenance scripts not executing on east region serverslikely time zone mismatch.	2/16/2025 Urgent	Closed - Resolved
11/26/2024 Error 7002: No response from servo motor controller on axis Ypossible hardware failure.	12/5/2024 High	In Progress

4/3/2025 Client unable to archive closed support ticketspermission role misconfiguration.	4/3/2025 Medium	Closed - Resolved
6/9/2024 Armature alignment reset required after shippingrequesting field calibration.	6/13/2024 High	On Hold
6/1/2024 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	6/4/2024 High	Closed
8/29/2024 New actuator exhibiting slow response in colder environmentsmaterial tolerance concern.	8/30/2024 Urgent	Cancelled
3/31/2025 Task scheduler running duplicate jobs on dual-robot configurationdeadlock conditions observed.	4/7/2025 Low	Open
3/23/2025 Load cell in robotic lifter reading zero under active payloadsuspected cable break.	3/24/2025 Medium	Closed - Resolved
9/13/2024 Remote shutdown of customer system initiated without proper command logpossible logging misfire.	9/23/2024 Medium	In Progress
12/22/2024 Motion sensor fault in entry-level AGVsuspected electromagnetic interference.	12/27/2024 Medium	Closed - Resolved
4/14/2025 Robot arm #4 failed precision test during QAtolerance exceeds threshold by 0.04 mm.	4/15/2025 High	On Hold
10/13/2024 Firmware rollback initiated unintentionallyclient device now stuck in bootloader loop.	10/21/2024 Low	Closed
5/11/2024 High-pitched tone coming from servo in model XR100engineering to review noise profile.	5/16/2024 High	On Hold
11/23/2024 HR database not syncing with shift handoff bot schedulermissing employee record.	12/2/2024 Medium	Closed - Resolved
9/6/2024 Wireless module upgrade caused latency spikepossible firmware mismatch.	9/8/2024 Urgent	Closed - Resolved
7/28/2024 Error 412 triggered during over-the-air update to robotic welding units in Southeast territory.	7/30/2024 Low	Open
3/5/2025 Unexpected motor vibration on high-speed units deployed in humid environments.	3/7/2025 High	Closed
10/16/2024 Overhead robotic crane misaligned after system updaterequesting recalibration walkthrough.	10/24/2024 Urgent	In Progress
5/22/2024 User permissions incorrectly assigned admin access granted to technician role.	5/24/2024 Medium	Cancelled
8/30/2024 Routine maintenance tag not updating in system despite completionworkflow integration error.	9/8/2024 Medium	Closed
9/22/2024 3D vision system under-picking SKUs from top shelvesimage recognition needs retraining.	9/27/2024 High	Cancelled
1/2/2025 Custom firmware deployment not stickingdevice reverts to factory version after reboot.	1/3/2025 Medium	On Hold
7/2/2024 Support agent unable to replicate power cycling bug reported on new Roboweld Plus series.	7/9/2024 High	Open
9/26/2024 Service report PDF not attaching to customer CRM recordautomation flow broken.	9/30/2024 Urgent	Closed - Resolved
11/19/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch.	11/24/2024 Low	In Progress
4/23/2024 Support team reports double charge on robotic part restockSLA breach inquiry pending.	4/30/2024 Medium	Closed - Resolved
12/29/2024 Discrepancy between scanned and delivered SKUspotential robotic misclassification event.	1/2/2025 High	Open
2/17/2025 Product loader mistiming drop-off with downstream conveyorsync pulse missing.	2/20/2025 Low	Closed - Resolved
11/30/2024 Voice command module failing to recognize commands with headset mic input.	12/8/2024 High	Closed - Resolved
12/27/2024 Downtime incorrectly logged as resolved in dashboardresolution timestamp error.	12/31/2024 Medium	Closed
12/8/2024 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	12/10/2024 Urgent	In Progress
6/14/2024 Scheduled maintenance scripts not executing on east region serverslikely time zone mismatch.	6/21/2024 High	Cancelled
7/6/2024 Error 7002: No response from servo motor controller on axis Ypossible hardware failure.	7/12/2024 Medium	On Hold
11/17/2024 Client unable to archive closed support ticketspermission role misconfiguration.	11/23/2024 Medium	Closed
1/26/2025 Armature alignment reset required after shipping requesting field calibration.	1/29/2025 Medium	Closed - Resolved
5/3/2024 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	5/4/2024 High	Cancelled

7/17/2024 New actuator exhibiting slow response in colder environmentsmaterial tolerance concern.	7/24/2024 High	Closed - Resolved
6/16/2024 Task scheduler running duplicate jobs on dual-robot configurationdeadlock conditions observed.	6/18/2024 Urgent	Open
4/12/2025 Load cell in robotic lifter reading zero under active payloadsuspected cable break.	4/21/2025 Low	In Progress
8/17/2024 Remote shutdown of customer system initiated without proper command logpossible logging misfire.	8/17/2024 High	On Hold
12/12/2024 Motion sensor fault in entry-level AGVsuspected electromagnetic interference.	12/20/2024 Low	Cancelled
6/16/2024 Robot arm #4 failed precision test during QAtolerance exceeds threshold by 0.04 mm.	6/18/2024 High	Open
8/10/2024 Firmware rollback initiated unintentionallyclient device now stuck in bootloader loop.	8/10/2024 Medium	Closed - Resolved
4/5/2025 High-pitched tone coming from servo in model XR100engineering to review noise profile.	4/7/2025 Urgent	In Progress
5/13/2024 HR database not syncing with shift handoff bot schedulermissing employee record.	5/22/2024 Medium	Closed - Resolved
11/17/2024 Wireless module upgrade caused latency spikepossible firmware mismatch.	11/19/2024 Low	On Hold
7/8/2024 Error 412 triggered during over-the-air update to robotic welding units in Southeast territory.	7/13/2024 Medium	Closed
11/15/2024 Unexpected motor vibration on high-speed units deployed in humid environments.	11/16/2024 Medium	Closed
1/10/2025 Overhead robotic crane misaligned after system updaterequesting recalibration walkthrough.	1/14/2025 High	In Progress
7/12/2024 User permissions incorrectly assigned admin access granted to technician role.	7/16/2024 High	Cancelled
7/21/2024 Routine maintenance tag not updating in system despite completionworkflow integration error.	7/29/2024 Urgent	On Hold
3/11/2025 3D vision system under-picking SKUs from top shelvesimage recognition needs retraining.	3/19/2025 Low	Closed - Resolved
4/27/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter.	5/5/2024 High	Closed - Resolved
3/27/2025 License expiration alerts not appearing for client adminmonitoring system inactive.	3/30/2025 Medium	Open
6/17/2024 Inventory report mislabeling robotics model numbersSKU logic misfire.	6/26/2024 Urgent	Cancelled
8/28/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing.	9/7/2024 Medium	On Hold
4/26/2024 Mobile control app crashing after recent OS updatecompatibility fix required.	4/29/2024 High	Open
3/28/2025 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt.	4/2/2025 Low	Closed - Resolved
1/11/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing.	1/17/2025 High	In Progress
2/20/2025 Latest patch rolled out to wrong robot model familyrollback request submitted.	2/24/2025 Urgent	Closed - Resolved
4/11/2025 API returning null values for order tracking endpointbackend request timing out.	4/13/2025 Medium	Closed
4/11/2025 Data not syncing across international locationstimezone setting discrepancies confirmed.	4/19/2025 Medium	Open
7/17/2024 Night shift override not deactivating during scheduled switchlogic conflict in script.	7/21/2024 High	Closed
2/8/2025 Technician override mode triggering false alarmsUI miscommunication suspected.	2/15/2025 Medium	In Progress
9/2/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted.	9/5/2024 High	On Hold
12/19/2024 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	12/26/2024 Medium	Closed - Resolved
4/4/2025 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected.	4/10/2025 High	Cancelled
4/4/2025 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected.	4/13/2025 Urgent	Closed - Resolved
7/5/2024 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions.	7/8/2024 Low	Open
11/8/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	11/14/2024 Urgent	Closed - Resolved

11/13/2024 Temperature sensor in robotic soldering unit reading above safe operating range.	11/22/2024 Low	In Progress
7/25/2024 Customer unable to submit service ticket via mobile portalUI issue on latest Android version.	7/27/2024 Medium	Closed - Resolved
1/29/2025 LED status indicator stuck in red despite system running normallyvisual false positive?	1/30/2025 Medium	Closed
2/12/2025 Customer states predictive maintenance alert was missedpossible alert suppression rule.	2/16/2025 High	Cancelled
12/28/2024 AI co-pilot interface displaying outdated warehouse inventory despite live API integration.	1/5/2025 High	On Hold
12/29/2024 System audit flagging unauthorized access attempt on robotics control API.	1/8/2025 High	Open
8/24/2024 Idle time tracking for warehouse units not logging correctlytelemetry data gap.	8/25/2024 Low	Closed - Resolved
3/28/2025 Diagnostic tool unable to communicate with legacy hardwareadapter may be required.	4/1/2025 High	Closed - Resolved
3/2/2025 Automated welding arm intermittently halts during high-heat cyclessuspected sensor calibration drift.	3/11/2025 Medium	Closed
8/7/2024 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken.	8/11/2024 Urgent	In Progress
6/20/2024 Battery drain accelerating on self-navigating picker botsclient requests hardware review.	6/23/2024 Medium	Cancelled
10/6/2024 Unexpected stop condition triggered during pallet rewrap routineinvestigating fault codes.	10/10/2024 High	On Hold
8/1/2024 Repeated '404 device not found' error on support dashboardbelieved to be ID mismatch.	8/9/2024 Low	In Progress
1/16/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration.	1/24/2025 High	On Hold
3/11/2025 Navigation system freezing mid-shiftpacket loss observed in Wi-Fi logs.	3/13/2025 Medium	Closed
5/23/2024 Unable to reset robotic arm to home positionreset protocol fails at step 3.	5/28/2024 Urgent	Closed - Resolved
3/15/2025 Customer service chatbot incorrectly routing requests about robotic arms to finance.	3/21/2025 Medium	Cancelled
8/1/2024 Customer account flagged as inactive during quarterly synccontract still in force until Q4.	8/10/2024 Urgent	Closed - Resolved
3/28/2025 Customer reports excessive heat on robotics control panelcooling fan test requested.	4/4/2025 High	Open
6/24/2024 Pick path optimization feature stuck in recalculating looplikely route matrix bug.	6/27/2024 Medium	Closed - Resolved
11/3/2024 Inconsistent barcode scanning during inbound sortationrequesting diagnostic logs.	11/7/2024 High	Open
6/10/2024 Issue syncing sales data from ERP into robotics supply chain dashboard.	6/17/2024 Low	Closed
1/15/2025 Billing dashboard showing duplicate line items for SLA renewalneeds manual reconciliation.	1/24/2025 Medium	In Progress
2/27/2025 Motion sensor fault in entry-level AGVsuspected electromagnetic interference.	3/7/2025 Low	On Hold
11/16/2024 System audit flagging unauthorized access attempt on robotics control API.	11/24/2024 Medium	Closed - Resolved
3/17/2025 Client unable to archive closed support ticketspermission role misconfiguration.	3/22/2025 Urgent	Cancelled
8/25/2024 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	8/31/2024 High	Cancelled
2/17/2025 License expiration alerts not appearing for client adminmonitoring system inactive.	2/21/2025 Medium	On Hold
4/11/2025 HR database not syncing with shift handoff bot schedulermissing employee record.	4/21/2025 High	Open
6/12/2024 Discrepancy between scanned and delivered SKUspotential robotic misclassification event.	6/17/2024 Urgent	Closed - Resolved
1/16/2025 Remote shutdown of customer system initiated without proper command logpossible logging misfire.	1/23/2025 Low	In Progress
12/30/2024 Inventory report mislabeling robotics model numbersSKU logic misfire.	1/6/2025 Medium	Closed - Resolved
2/6/2025 Task scheduler running duplicate jobs on dual-robot configurationdeadlock conditions observed.	2/14/2025 Medium	Closed
4/9/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions.	4/16/2025 High	On Hold

10/13/2024 Unexpected stop condition triggered during pallet rewrap routineinvestigating fault codes.	10/17/2024 High	Open
11/21/2024 Idle time tracking for warehouse units not logging correctlytelemetry data gap.	11/27/2024 High	Closed - Resolved
8/24/2024 Return unit not accepting scanned QR codesoptical reader needs recalibration.	8/30/2024 Low	In Progress
8/1/2024 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken.	8/8/2024 Medium	Closed - Resolved
3/21/2025 Battery drain accelerating on self-navigating picker botsclient requests hardware review.	3/29/2025 Urgent	Closed
6/27/2024 Battery health metrics not populating in regional dashboardtelemetry stream missing.	7/5/2024 High	Cancelled
1/26/2025 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter.	2/4/2025 Medium	Closed - Resolved
1/30/2025 Scheduled maintenance scripts not executing on east region serverslikely time zone mismatch.	1/31/2025 Low	On Hold
4/21/2025 Repeated '404 device not found' error on support dashboardbelieved to be ID mismatch.	4/27/2025 Medium	Closed
5/2/2024 Unexpected motor vibration on high-speed units deployed in humid environments.	5/10/2024 Urgent	Closed - Resolved
5/5/2024 Routine maintenance tag not updating in system despite completionworkflow integration error.	5/8/2024 High	Cancelled
1/8/2025 Support agent unable to replicate power cycling bug reported on new Roboweld Plus series.	1/9/2025 Medium	Open
9/15/2024 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected.	9/18/2024 High	In Progress
5/8/2024 New actuator exhibiting slow response in colder environmentsmaterial tolerance concern.	5/8/2024 Medium	Cancelled
7/14/2024 Downtime incorrectly logged as resolved in dashboardresolution timestamp error.	7/19/2024 High	Open
6/21/2024 Navigation system freezing mid-shiftpacket loss observed in Wi-Fi logs.	6/24/2024 Medium	In Progress
3/28/2025 Service report PDF not attaching to customer CRM recordautomation flow broken.	3/31/2025 High	Closed - Resolved
12/26/2024 Customer unable to submit service ticket via mobile portalUI issue on latest Android version.	12/31/2024 Urgent	On Hold
6/19/2024 Issue syncing sales data from ERP into robotics supply chain dashboard.	6/24/2024 Low	Closed
10/13/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt.	10/22/2024 High	Closed - Resolved
2/16/2025 Wireless module upgrade caused latency spikepossible firmware mismatch.	2/16/2025 Low	Closed - Resolved
3/25/2025 Mobile control app crashing after recent OS updatecompatibility fix required.	3/27/2025 High	Open
4/4/2025 Firmware rollback initiated unintentionallyclient device now stuck in bootloader loop.	4/13/2025 Urgent	Closed
6/8/2024 Support team reports double charge on robotic part restockSLA breach inquiry pending.	6/10/2024 Medium	In Progress
7/10/2024 Product loader mistiming drop-off with downstream conveyorsync pulse missing.	7/16/2024 Medium	Cancelled
12/12/2024 Automated welding arm intermittently halts during high-heat cyclessuspected sensor calibration drift.	12/20/2024 High	On Hold
8/16/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted.	8/19/2024 Low	Closed - Resolved
5/4/2024 Night shift override not deactivating during scheduled switchlogic conflict in script.	5/10/2024 High	Closed - Resolved
6/16/2024 Voice command module failing to recognize commands with headset mic input.	6/25/2024 Urgent	Cancelled
12/15/2024 Customer service chatbot incorrectly routing requests about robotic arms to finance.	12/22/2024 Medium	Open
7/27/2024 Inconsistent barcode scanning during inbound sortationrequesting diagnostic logs.	8/2/2024 Medium	In Progress
8/11/2024 Overhead robotic crane misaligned after system updaterequesting recalibration walkthrough.	8/17/2024 Medium	Closed - Resolved
5/13/2024 Robot arm #4 failed precision test during QAtolerance exceeds threshold by 0.04 mm.	5/19/2024 Medium	On Hold
9/8/2024 Customer states predictive maintenance alert was missedpossible alert suppression rule.	9/16/2024 High	Closed

8/2/2024 AI co-pilot interface displaying outdated warehouse inventory despite live API integration.	8/10/2024 Low	Cancelled
9/20/2024 Technician override mode triggering false alarmsUI miscommunication suspected.	9/27/2024 High	Open
11/19/2024 Pick path optimization feature stuck in recalculating looplikely route matrix bug.	11/27/2024 Urgent	In Progress
12/19/2024 High-pitched tone coming from servo in model XR100engineering to review noise profile.	12/22/2024 High	Closed - Resolved
5/7/2024 Data not syncing across international locationstimezone setting discrepancies confirmed.	5/8/2024 High	On Hold
11/25/2024 3D vision system under-picking SKUs from top shelvesimage recognition needs retraining.	11/26/2024 Urgent	Closed
5/7/2024 Custom firmware deployment not sticking device reverts to factory version after reboot.	5/14/2024 Low	Closed - Resolved
12/30/2024 Customer account flagged as inactive during quarterly synccontract still in force until Q4.	1/6/2025 Medium	In Progress
6/25/2024 Armature alignment reset required after shippingrequesting field calibration.	7/5/2024 Medium	On Hold
5/14/2024 Error 412 triggered during over-the-air update to robotic welding units in Southeast territory.	5/21/2024 High	Closed
3/18/2025 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	3/23/2025 Medium	Closed - Resolved
1/24/2025 Unable to reset robotic arm to home positionreset protocol fails at step 3.	1/27/2025 Urgent	Cancelled
1/14/2025 Temperature sensor in robotic soldering unit reading above safe operating range.	1/15/2025 High	Closed - Resolved
4/11/2025 Load cell in robotic lifter reading zero under active payloadsuspected cable break.	4/20/2025 Medium	Open
3/18/2025 Billing dashboard showing duplicate line items for SLA renewalneeds manual reconciliation.	3/28/2025 Low	On Hold
12/18/2024 User permissions incorrectly assigned admin access granted to technician role.	12/21/2024 Urgent	Open
11/22/2024 Diagnostic tool unable to communicate with legacy hardwareadapter may be required.	11/23/2024 Low	Closed - Resolved
10/24/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch.	10/27/2024 Medium	Closed - Resolved
4/29/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	4/30/2024 High	Closed
1/5/2025 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing.	1/14/2025 Medium	In Progress
6/7/2024 Latest patch rolled out to wrong robot model familyrollback request submitted.	6/10/2024 High	Cancelled
4/6/2025 Customer reports excessive heat on robotics control panelcooling fan test requested.	4/8/2025 High	Cancelled
6/16/2024 API returning null values for order tracking endpointbackend request timing out.	6/25/2024 Medium	On Hold
10/10/2024 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	10/17/2024 High	Open
5/22/2024 Error 7002: No response from servo motor controller on axis Ypossible hardware failure.	5/23/2024 Urgent	Closed - Resolved
11/6/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected.	11/6/2024 Low	Closed - Resolved
5/9/2024 LED status indicator stuck in red despite system running normallyvisual false positive?	5/19/2024 Medium	Closed
9/4/2024 Inventory report mislabeling robotics model numbersSKU logic misfire.	9/4/2024 High	In Progress
9/26/2024 Night shift override not deactivating during scheduled switchlogic conflict in script.	9/26/2024 Medium	Closed
9/30/2024 User permissions incorrectly assigned admin access granted to technician role.	10/9/2024 Urgent	In Progress
2/26/2025 Picking robot skipping assigned aisle in optimization routemap index might be corrupted.	2/28/2025 High	Cancelled
4/14/2025 Idle time tracking for warehouse units not logging correctlytelemetry data gap.	4/16/2025 Medium	On Hold
10/27/2024 Downtime incorrectly logged as resolved in dashboardresolution timestamp error.	11/2/2024 Low	Open
10/27/2024 Battery health metrics not populating in regional dashboardtelemetry stream missing.	11/1/2024 High	Closed - Resolved

2/25/2025 Latest patch rolled out to wrong robot model familyrollback request submitted.	3/2/2025 Urgent	Closed - Resolved
12/16/2024 Billing dashboard showing duplicate line items for SLA renewalneeds manual reconciliation.	12/17/2024 Low	On Hold
11/5/2024 System audit flagging unauthorized access attempt on robotics control API.	11/11/2024 Medium	Closed - Resolved
5/18/2024 Customer account flagged as inactive during quarterly synccontract still in force until Q4.	5/19/2024 Medium	Cancelled
11/30/2024 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	12/6/2024 High	Closed - Resolved
6/8/2024 Motion sensor fault in entry-level AGVsuspected electromagnetic interference.	6/12/2024 Medium	Open
10/31/2024 High-pitched tone coming from servo in model XR100engineering to review noise profile.	11/4/2024 Medium	Closed
1/10/2025 Wireless module upgrade caused latency spikepossible firmware mismatch.	1/15/2025 High	In Progress
8/8/2024 Unable to reset robotic arm to home positionreset protocol fails at step 3.	8/9/2024 Low	Closed - Resolved
9/16/2024 Technician override mode triggering false alarmsUI miscommunication suspected.	9/21/2024 High	In Progress
10/24/2024 Customer service chatbot incorrectly routing requests about robotic arms to finance.	10/31/2024 Urgent	Closed - Resolved
8/10/2024 HR database not syncing with shift handoff bot schedulermissing employee record.	8/16/2024 Urgent	On Hold
3/7/2025 Support team reports double charge on robotic part restockSLA breach inquiry pending.	3/15/2025 Low	Closed
3/14/2025 Unexpected motor vibration on high-speed units deployed in humid environments.	3/21/2025 Medium	Cancelled
8/8/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter.	8/15/2024 Medium	Open
1/15/2025 Service report PDF not attaching to customer CRM recordautomation flow broken.	1/21/2025 High	Closed - Resolved
5/21/2024 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions.	5/23/2024 High	Open
8/2/2024 License expiration alerts not appearing for client adminmonitoring system inactive.	8/11/2024 Low	In Progress
3/8/2025 Automated welding arm intermittently halts during high-heat cyclessuspected sensor calibration drift.	3/17/2025 Medium	On Hold
4/22/2025 Pick path optimization feature stuck in recalculating looplikely route matrix bug.	4/28/2025 Urgent	Closed
6/18/2024 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected.	6/26/2024 High	Closed - Resolved
4/4/2025 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	4/13/2025 Medium	Cancelled
11/26/2024 Inconsistent barcode scanning during inbound sortationrequesting diagnostic logs.	11/28/2024 High	On Hold
6/1/2024 Custom firmware deployment not stickingdevice reverts to factory version after reboot.	6/9/2024 Medium	Closed
6/27/2024 Client unable to archive closed support ticketspermission role misconfiguration.	7/5/2024 High	Closed - Resolved
8/28/2024 Armature alignment reset required after shippingrequesting field calibration.	9/2/2024 High	Cancelled
1/20/2025 New actuator exhibiting slow response in colder environmentsmaterial tolerance concern.	1/21/2025 Urgent	Closed - Resolved
3/1/2025 Support agent unable to replicate power cycling bug reported on new Roboweld Plus series.	3/8/2025 Low	Open
3/28/2025 LED status indicator stuck in red despite system running normallyvisual false positive?	3/31/2025 Medium	In Progress
7/15/2024 Load cell in robotic lifter reading zero under active payloadsuspected cable break.	7/19/2024 High	Closed - Resolved
9/11/2024 API returning null values for order tracking endpointbackend request timing out.	9/19/2024 Urgent	In Progress
11/20/2024 Return unit not accepting scanned QR codesoptical reader needs recalibration.	11/21/2024 Low	Closed - Resolved
8/13/2024 Customer states predictive maintenance alert was missedpossible alert suppression rule.	8/18/2024 Medium	On Hold
9/24/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	9/26/2024 Medium	Closed

10/30/2024 Error 412 triggered during over-the-air update to robotic welding units in Southeast territory.	11/5/2024 High	Cancelled
3/24/2025 AI co-pilot interface displaying outdated warehouse inventory despite live API integration.	3/28/2025 Medium	Open
5/12/2024 Battery drain accelerating on self-navigating picker botsclient requests hardware review.	5/19/2024 Low	Closed - Resolved
3/31/2025 Firmware rollback initiated unintentionallyclient device now stuck in bootloader loop.	4/3/2025 High	Cancelled
8/19/2024 Error 7002: No response from servo motor controller on axis Ypossible hardware failure.	8/28/2024 Medium	Closed - Resolved
6/15/2024 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	6/18/2024 Urgent	Open
5/31/2024 Customer reports excessive heat on robotics control panelcooling fan test requested.	6/4/2024 High	Closed
3/5/2025 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt.	3/7/2025 Medium	In Progress
4/22/2025 Unexpected stop condition triggered during pallet rewrap routineinvestigating fault codes.	4/29/2025 Urgent	On Hold
12/4/2024 Task scheduler running duplicate jobs on dual-robot configurationdeadlock conditions observed.	12/6/2024 High	Closed
8/11/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing.	8/20/2024 Medium	In Progress
1/25/2025 Overhead robotic crane misaligned after system updaterequesting recalibration walkthrough.	1/27/2025 Low	Cancelled
7/14/2024 Routine maintenance tag not updating in system despite completionworkflow integration error.	7/20/2024 High	On Hold
2/22/2025 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected.	2/24/2025 High	Open
3/29/2025 Voice command module failing to recognize commands with headset mic input.	3/30/2025 Urgent	Closed - Resolved
11/13/2024 Customer unable to submit service ticket via mobile portalUI issue on latest Android version.	11/16/2024 Medium	Closed - Resolved
11/27/2024 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken.	12/5/2024 High	Open
12/27/2024 Remote shutdown of customer system initiated without proper command logpossible logging misfire.	1/2/2025 Low	Closed
5/21/2024 3D vision system under-picking SKUs from top shelvesimage recognition needs retraining.	5/26/2024 Urgent	In Progress
9/4/2024 Temperature sensor in robotic soldering unit reading above safe operating range.	9/14/2024 High	Cancelled
3/1/2025 Data not syncing across international locationstimezone setting discrepancies confirmed.	3/5/2025 Medium	On Hold
8/23/2024 Mobile control app crashing after recent OS updatecompatibility fix required.	8/30/2024 Low	Closed - Resolved
8/25/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch.	8/27/2024 High	Open
2/11/2025 Product loader mistiming drop-off with downstream conveyorsync pulse missing.	2/15/2025 Medium	In Progress
2/11/2025 Scheduled maintenance scripts not executing on east region serverslikely time zone mismatch.	2/12/2025 Medium	Closed - Resolved
4/18/2025 Repeated '404 device not found' error on support dashboardbelieved to be ID mismatch.	4/24/2025 Urgent	On Hold
10/16/2024 Diagnostic tool unable to communicate with legacy hardwareadapter may be required.	10/18/2024 Medium	Closed
8/7/2024 Discrepancy between scanned and delivered SKUspotential robotic misclassification event.	8/9/2024 High	Closed - Resolved
9/30/2024 Robot arm #4 failed precision test during QAtolerance exceeds threshold by 0.04 mm.	10/4/2024 Low	Cancelled
6/8/2024 Navigation system freezing mid-shiftpacket loss observed in Wi-Fi logs.	6/14/2024 High	In Progress
8/1/2024 Wireless module upgrade caused latency spikepossible firmware mismatch.	8/8/2024 Low	Cancelled
4/25/2024 Overhead robotic crane misaligned after system updaterequesting recalibration walkthrough.	4/29/2024 High	On Hold
12/29/2024 Automated welding arm intermittently halts during high-heat cyclessuspected sensor calibration drift.	1/4/2025 Urgent	Closed - Resolved
4/23/2024 HR database not syncing with shift handoff bot schedulermissing employee record.	4/27/2024 Medium	Closed - Resolved

8/24/2024 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	8/27/2024 Medium	Open
7/19/2024 Temperature sensor in robotic soldering unit reading above safe operating range.	7/25/2024 High	Closed
5/29/2024 Pick path optimization feature stuck in recalculating looplikely route matrix bug.	6/4/2024 High	Closed - Resolved
12/5/2024 Inconsistent barcode scanning during inbound sortation requesting diagnostic logs.	12/6/2024 Low	Closed - Resolved
11/6/2024 Idle time tracking for warehouse units not logging correctlytelemetry data gap.	11/14/2024 Medium	Open
6/22/2024 License expiration alerts not appearing for client adminmonitoring system inactive.	6/26/2024 Urgent	Closed
11/1/2024 Battery health metrics not populating in regional dashboardtelemetry stream missing.	11/6/2024 High	In Progress
10/15/2024 Unexpected motor vibration on high-speed units deployed in humid environments.	10/24/2024 Medium	Cancelled
8/26/2024 Robot arm #4 failed precision test during QAtolerance exceeds threshold by 0.04 mm.	9/3/2024 High	On Hold
4/7/2025 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter.	4/7/2025 Urgent	Closed
8/3/2024 Routine maintenance tag not updating in system despite completionworkflow integration error.	8/9/2024 Low	Cancelled
8/22/2024 New actuator exhibiting slow response in colder environmentsmaterial tolerance concern.	8/29/2024 Medium	Open
12/10/2024 User permissions incorrectly assigned admin access granted to technician role.	12/11/2024 High	Closed - Resolved
8/27/2024 Custom firmware deployment not stickingdevice reverts to factory version after reboot.	9/4/2024 Medium	In Progress
6/29/2024 Service report PDF not attaching to customer CRM recordautomation flow broken.	7/6/2024 Urgent	Closed - Resolved
5/19/2024 Error 7002: No response from servo motor controller on axis Ypossible hardware failure.	5/28/2024 Low	On Hold
1/18/2025 Customer reports excessive heat on robotics control panelcooling fan test requested.	1/27/2025 Medium	In Progress
6/6/2024 Customer unable to submit service ticket via mobile portalUI issue on latest Android version.	6/8/2024 High	Closed - Resolved
10/16/2024 Mobile control app crashing after recent OS updatecompatibility fix required.	10/21/2024 Medium	On Hold
4/11/2025 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch.	4/18/2025 High	Closed
11/1/2024 LED status indicator stuck in red despite system running normallyvisual false positive?	11/7/2024 Medium	Cancelled
7/4/2024 System audit flagging unauthorized access attempt on robotics control API.	7/9/2024 Medium	Open
10/4/2024 Issue syncing sales data from ERP into robotics supply chain dashboard.	10/7/2024 High	Closed - Resolved
10/7/2024 Firmware rollback initiated unintentionallyclient device now stuck in bootloader loop.	10/9/2024 High	Closed - Resolved
3/26/2025 Error 412 triggered during over-the-air update to robotic welding units in Southeast territory.	3/31/2025 Urgent	Closed - Resolved
12/13/2024 API returning null values for order tracking endpointbackend request timing out.	12/14/2024 Low	Closed
9/26/2024 3D vision system under-picking SKUs from top shelvesimage recognition needs retraining.	9/28/2024 Medium	In Progress
3/16/2025 Product loader mistiming drop-off with downstream conveyorsync pulse missing.	3/23/2025 High	Cancelled
1/13/2025 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	1/18/2025 Low	On Hold
6/7/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing.	6/11/2024 High	Open
3/28/2025 High-pitched tone coming from servo in model XR100engineering to review noise profile.	4/1/2025 Medium	Closed - Resolved
9/29/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected.	10/8/2024 Urgent	On Hold
2/10/2025 Load cell in robotic lifter reading zero under active payloadsuspected cable break.	2/17/2025 High	Closed
1/12/2025 Customer service chatbot incorrectly routing requests about robotic arms to finance.	1/12/2025 Urgent	Cancelled

6/9/2024 Support team reports double charge on robotic part restockSLA breach inquiry pending.	6/17/2024 Low	Open
3/30/2025 AI co-pilot interface displaying outdated warehouse inventory despite live API integration.	3/30/2025 Medium	Closed - Resolved
5/10/2024 Technician override mode triggering false alarmsUI miscommunication suspected.	5/11/2024 Medium	In Progress
10/5/2024 Scheduled maintenance scripts not executing on east region serverslikely time zone mismatch.	10/14/2024 High	In Progress
3/11/2025 Customer account flagged as inactive during quarterly synccontract still in force until Q4.	3/12/2025 High	Closed - Resolved
3/22/2025 Repeated '404 device not found' error on support dashboardbelieved to be ID mismatch.	3/27/2025 Low	Closed
9/14/2024 Remote shutdown of customer system initiated without proper command logpossible logging misfire.	9/18/2024 High	Cancelled
12/29/2024 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected.	1/1/2025 Urgent	On Hold
5/25/2024 Unexpected stop condition triggered during pallet rewrap routineinvestigating fault codes.	5/25/2024 Medium	Open
9/7/2024 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken.	9/10/2024 Medium	Closed - Resolved
1/15/2025 Support agent unable to replicate power cycling bug reported on new Roboweld Plus series.	1/23/2025 Medium	Open
6/19/2024 Unable to reset robotic arm to home positionreset protocol fails at step 3.	6/28/2024 Urgent	Closed - Resolved
12/23/2024 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions.	12/29/2024 High	Closed - Resolved
6/16/2024 Data not syncing across international locationstimezone setting discrepancies confirmed.	6/16/2024 Medium	Closed
6/8/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	6/12/2024 Low	In Progress
1/8/2025 Navigation system freezing mid-shiftpacket loss observed in Wi-Fi logs.	1/13/2025 High	Cancelled
8/31/2024 Armature alignment reset required after shippingrequesting field calibration.	8/31/2024 Medium	On Hold
11/6/2024 Discrepancy between scanned and delivered SKUspotential robotic misclassification event.	11/10/2024 High	Closed - Resolved
12/11/2024 Night shift override not deactivating during scheduled switchlogic conflict in script.	12/18/2024 High	Cancelled
4/17/2025 Latest patch rolled out to wrong robot model familyrollback request submitted.	4/17/2025 Urgent	Open
5/28/2024 Voice command module failing to recognize commands with headset mic input.	5/29/2024 Low	In Progress
2/22/2025 Battery drain accelerating on self-navigating picker botsclient requests hardware review.	2/26/2025 Medium	Closed - Resolved
3/27/2025 Billing dashboard showing duplicate line items for SLA renewalneeds manual reconciliation.	3/31/2025 Medium	On Hold
3/19/2025 Motion sensor fault in entry-level AGVsuspected electromagnetic interference.	3/25/2025 Medium	Closed
4/9/2025 Downtime incorrectly logged as resolved in dashboardresolution timestamp error.	4/15/2025 High	Closed - Resolved
8/21/2024 Return unit not accepting scanned QR codesoptical reader needs recalibration.	8/27/2024 High	Cancelled
8/8/2024 Diagnostic tool unable to communicate with legacy hardwareadapter may be required.	8/13/2024 Urgent	Closed - Resolved
2/11/2025 Inventory report mislabeling robotics model numbersSKU logic misfire.	2/17/2025 Low	Open
11/24/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted.	11/26/2024 Medium	In Progress
5/15/2024 Client unable to archive closed support ticketspermission role misconfiguration.	5/15/2024 Low	On Hold
5/9/2024 Task scheduler running duplicate jobs on dual-robot configurationdeadlock conditions observed.	5/11/2024 High	Closed
9/29/2024 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	10/1/2024 Medium	Closed - Resolved
11/27/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt.	12/6/2024 Urgent	Open
8/17/2024 Customer states predictive maintenance alert was missedpossible alert suppression rule.	8/19/2024 High	In Progress

5/13/2024 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected.	5/15/2024 Medium	On Hold
2/5/2025 Error 412 triggered during over-the-air update to robotic welding units in Southeast territory.	2/11/2025 High	Closed
6/8/2024 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions.	6/17/2024 High	Closed - Resolved
8/1/2024 Battery health metrics not populating in regional dashboardtelemetry stream missing.	8/10/2024 Urgent	Cancelled
11/12/2024 AI co-pilot interface displaying outdated warehouse inventory despite live API integration.	11/20/2024 Low	Closed
10/5/2024 Return unit not accepting scanned QR codesoptical reader needs recalibration.	10/12/2024 Medium	In Progress
5/12/2024 Support team reports double charge on robotic part restockSLA breach inquiry pending.	5/15/2024 High	On Hold
3/9/2025 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter.	3/16/2025 Low	Closed - Resolved
1/27/2025 Firmware rollback initiated unintentionallyclient device now stuck in bootloader loop.	1/29/2025 High	Cancelled
11/13/2024 Custom firmware deployment not sticking device reverts to factory version after reboot.	11/14/2024 Urgent	Closed - Resolved
9/23/2024 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	10/1/2024 Medium	Open
3/7/2025 Downtime incorrectly logged as resolved in dashboardresolution timestamp error.	3/17/2025 Medium	Closed
1/7/2025 HR database not syncing with shift handoff bot schedulermissing employee record.	1/9/2025 Urgent	Cancelled
10/27/2024 Temperature sensor in robotic soldering unit reading above safe operating range.	11/4/2024 Low	On Hold
12/19/2024 Automated welding arm intermittently halts during high-heat cyclessuspected sensor calibration drift.	12/19/2024 Medium	Open
11/14/2024 Data not syncing across international locationstimezone setting discrepancies confirmed.	11/20/2024 High	Closed - Resolved
5/27/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing.	5/28/2024 Medium	In Progress
12/6/2024 Repeated '404 device not found' error on support dashboardbelieved to be ID mismatch.	12/7/2024 High	Closed - Resolved
10/2/2024 Voice command module failing to recognize commands with headset mic input.	10/5/2024 High	Closed - Resolved
8/23/2024 Scheduled maintenance scripts not executing on east region serverslikely time zone mismatch.	8/29/2024 High	Closed - Resolved
6/3/2024 Inconsistent barcode scanning during inbound sortationrequesting diagnostic logs.	6/6/2024 Urgent	Open
2/3/2025 Customer reports robotic forklift overshooting dock alignment camera offset suspected.	2/10/2025 Low	Closed
11/13/2024 Support agent unable to replicate power cycling bug reported on new Roboweld Plus series.	11/14/2024 Medium	In Progress
3/24/2025 Mobile control app crashing after recent OS updatecompatibility fix required.	4/1/2025 Medium	Cancelled
5/16/2024 Service report PDF not attaching to customer CRM recordautomation flow broken.	5/17/2024 High	On Hold
8/19/2024 API returning null values for order tracking endpointbackend request timing out.	8/19/2024 Low	On Hold
3/19/2025 Robot arm #4 failed precision test during QAtolerance exceeds threshold by 0.04 mm.	3/25/2025 High	Open
11/29/2024 Pick path optimization feature stuck in recalculating looplikely route matrix bug.	12/9/2024 Urgent	Closed - Resolved
1/20/2025 Customer service chatbot incorrectly routing requests about robotic arms to finance.	1/25/2025 Medium	Closed - Resolved
8/1/2024 System audit flagging unauthorized access attempt on robotics control API.	8/11/2024 Medium	Closed
1/3/2025 Customer states predictive maintenance alert was missedpossible alert suppression rule.	1/8/2025 Low	In Progress
7/2/2024 Customer account flagged as inactive during quarterly synccontract still in force until Q4.	7/8/2024 Medium	Cancelled
9/1/2024 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken.	9/8/2024 High	In Progress
8/10/2024 Armature alignment reset required after shippingrequesting field calibration.	8/14/2024 Medium	Closed - Resolved

7/3/2024 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	7/6/2024 High	On Hold
1/7/2025 Discrepancy between scanned and delivered SKUspotential robotic misclassification event.	1/12/2025 Urgent	Closed
7/27/2024 Issue syncing sales data from ERP into robotics supply chain dashboard.	8/5/2024 Medium	Cancelled
2/3/2025 LED status indicator stuck in red despite system running normallyvisual false positive?	2/3/2025 Medium	Open
10/26/2024 Overhead robotic crane misaligned after system updaterequesting recalibration walkthrough.	10/30/2024 High	Closed - Resolved
5/15/2024 Billing dashboard showing duplicate line items for SLA renewalneeds manual reconciliation.	5/21/2024 High	In Progress
11/2/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt.	11/6/2024 Urgent	On Hold
8/27/2024 Routine maintenance tag not updating in system despite completionworkflow integration error.	9/1/2024 Low	Closed - Resolved
11/22/2024 Unexpected stop condition triggered during pallet rewrap routineinvestigating fault codes.	11/26/2024 Urgent	Cancelled
3/3/2025 Client unable to archive closed support ticketspermission role misconfiguration.	3/6/2025 Medium	Closed - Resolved
8/3/2024 Night shift override not deactivating during scheduled switchlogic conflict in script.	8/5/2024 High	Open
3/19/2025 Unable to reset robotic arm to home positionreset protocol fails at step 3.	3/21/2025 Low	Closed
1/21/2025 User permissions incorrectly assigned admin access granted to technician role.	1/28/2025 High	Closed
5/7/2024 High-pitched tone coming from servo in model XR100engineering to review noise profile.	5/8/2024 Medium	In Progress
3/12/2025 Wireless module upgrade caused latency spikepossible firmware mismatch.	3/16/2025 High	Cancelled
9/11/2024 Latest patch rolled out to wrong robot model familyrollback request submitted.	9/16/2024 Low	On Hold
7/13/2024 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	7/22/2024 High	Closed - Resolved
11/27/2024 Unexpected motor vibration on high-speed units deployed in humid environments.	12/7/2024 Medium	Closed - Resolved
10/4/2024 Motion sensor fault in entry-level AGVsuspected electromagnetic interference.	10/9/2024 Urgent	Open
4/26/2024 Customer unable to submit service ticket via mobile portalUI issue on latest Android version.	5/1/2024 Medium	Closed
9/18/2024 Task scheduler running duplicate jobs on dual-robot configurationdeadlock conditions observed.	9/18/2024 Medium	Cancelled
6/6/2024 Remote shutdown of customer system initiated without proper command logpossible logging misfire.	6/10/2024 Medium	Open
6/3/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch.	6/10/2024 High	Closed - Resolved
8/6/2024 Technician override mode triggering false alarmsUI miscommunication suspected.	8/14/2024 High	In Progress
6/19/2024 3D vision system under-picking SKUs from top shelvesimage recognition needs retraining.	6/21/2024 Urgent	Closed - Resolved
12/26/2024 Product loader mistiming drop-off with downstream conveyorsync pulse missing.	1/5/2025 Low	On Hold
4/21/2025 Diagnostic tool unable to communicate with legacy hardwareadapter may be required.	4/22/2025 Urgent	In Progress
1/5/2025 New actuator exhibiting slow response in colder environmentsmaterial tolerance concern.	1/11/2025 Low	Cancelled
7/9/2024 License expiration alerts not appearing for client adminmonitoring system inactive.	7/16/2024 Medium	On Hold
7/10/2024 Navigation system freezing mid-shiftpacket loss observed in Wi-Fi logs.	7/15/2024 High	Closed - Resolved
4/27/2024 Battery drain accelerating on self-navigating picker botsclient requests hardware review.	4/30/2024 Medium	Closed - Resolved
12/11/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	12/13/2024 High	Open
4/20/2025 Picking robot skipping assigned aisle in optimization routemap index might be corrupted.	4/23/2025 High	Closed
1/19/2025 Load cell in robotic lifter reading zero under active payloadsuspected cable break.	1/20/2025 Low	Cancelled

6/3/2024 Error 7002: No response from servo motor controller on axis Ypossible hardware failure.	6/5/2024 Medium	On Hold
9/8/2024 Customer reports excessive heat on robotics control panelcooling fan test requested.	9/18/2024 Urgent	Open
8/28/2024 Inventory report mislabeling robotics model numbersSKU logic misfire.	9/1/2024 High	Closed - Resolved
11/7/2024 Idle time tracking for warehouse units not logging correctlytelemetry data gap.	11/9/2024 Medium	Closed - Resolved
4/26/2024 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	5/1/2024 High	Closed
7/13/2024 Robot arm #4 failed precision test during QAtolerance exceeds threshold by 0.04 mm.	7/16/2024 Medium	In Progress
1/28/2025 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected.	2/3/2025 Low	Cancelled
10/23/2024 Downtime incorrectly logged as resolved in dashboardresolution timestamp error.	10/25/2024 High	Closed - Resolved
3/29/2025 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing.	3/29/2025 Medium	Open
7/1/2024 Motion sensor fault in entry-level AGVsuspected electromagnetic interference.	7/1/2024 Urgent	In Progress
12/21/2024 Custom firmware deployment not stickingdevice reverts to factory version after reboot.	12/27/2024 Low	On Hold
8/8/2024 Service report PDF not attaching to customer CRM recordautomation flow broken.	8/18/2024 High	Closed
7/28/2024 HR database not syncing with shift handoff bot schedulermissing employee record.	8/3/2024 Medium	Closed - Resolved
2/16/2025 AI co-pilot interface displaying outdated warehouse inventory despite live API integration.	2/19/2025 Urgent	On Hold
8/16/2024 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected.	8/22/2024 Medium	Closed - Resolved
6/26/2024 Armature alignment reset required after shippingrequesting field calibration.	6/29/2024 High	Closed - Resolved
6/13/2024 Voice command module failing to recognize commands with headset mic input.	6/19/2024 Urgent	Open
8/19/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch.	8/22/2024 Low	Closed
10/24/2024 API returning null values for order tracking endpointbackend request timing out.	10/26/2024 Medium	In Progress
5/8/2024 Data not syncing across international locationstimezone setting discrepancies confirmed.	5/14/2024 Medium	Cancelled
7/28/2024 Discrepancy between scanned and delivered SKUspotential robotic misclassification event.	8/6/2024 High	Cancelled
3/25/2025 Battery drain accelerating on self-navigating picker botsclient requests hardware review.	3/29/2025 High	On Hold
3/31/2025 High-pitched tone coming from servo in model XR100engineering to review noise profile.	4/4/2025 High	Open
8/24/2024 Customer account flagged as inactive during quarterly synccontract still in force until Q4.	8/30/2024 Medium	Closed - Resolved
1/25/2025 LED status indicator stuck in red despite system running normallyvisual false positive?	2/1/2025 High	Closed - Resolved
11/10/2024 User permissions incorrectly assigned admin access granted to technician role.	11/18/2024 Low	Closed
9/26/2024 Scheduled maintenance scripts not executing on east region serverslikely time zone mismatch.	10/3/2024 Medium	In Progress
5/7/2024 Client unable to archive closed support ticketspermission role misconfiguration.	5/11/2024 Urgent	Open
4/8/2025 Unexpected motor vibration on high-speed units deployed in humid environments.	4/14/2025 Urgent	In Progress
6/29/2024 Inventory report mislabeling robotics model numbersSKU logic misfire.	7/9/2024 Low	On Hold
3/12/2025 Wireless module upgrade caused latency spikepossible firmware mismatch.	3/16/2025 Medium	Closed
7/29/2024 Repeated '404 device not found' error on support dashboardbelieved to be ID mismatch.	8/2/2024 High	Closed - Resolved
1/9/2025 Overhead robotic crane misaligned after system updaterequesting recalibration walkthrough.	1/13/2025 Medium	Cancelled
1/28/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions.	2/7/2025 High	Closed - Resolved

9/18/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt.	9/18/2024 Low	Closed
6/27/2024 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	7/1/2024 Medium	In Progress
12/3/2024 System audit flagging unauthorized access attempt on robotics control API.	12/4/2024 Medium	Cancelled
5/3/2024 Customer unable to submit service ticket via mobile portalUI issue on latest Android version.	5/12/2024 High	On Hold
2/22/2025 Error 7002: No response from servo motor controller on axis Ypossible hardware failure.	3/3/2025 High	Closed - Resolved
6/29/2024 3D vision system under-picking SKUs from top shelvesimage recognition needs retraining.	7/2/2024 Urgent	Closed - Resolved
4/8/2025 Inconsistent barcode scanning during inbound sortationrequesting diagnostic logs.	4/10/2025 Urgent	Open
11/26/2024 Support agent unable to replicate power cycling bug reported on new Roboweld Plus series.	12/3/2024 Low	Closed - Resolved
9/27/2024 Issue syncing sales data from ERP into robotics supply chain dashboard.	10/1/2024 Medium	Closed
4/24/2024 Idle time tracking for warehouse units not logging correctlytelemetry data gap.	5/3/2024 High	Cancelled
10/10/2024 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	10/12/2024 Medium	On Hold
3/29/2025 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter.	3/29/2025 High	Open
9/7/2024 Load cell in robotic lifter reading zero under active payloadsuspected cable break.	9/12/2024 Urgent	Closed - Resolved
11/21/2024 Remote shutdown of customer system initiated without proper command logpossible logging misfire.	11/28/2024 Medium	In Progress
10/16/2024 License expiration alerts not appearing for client adminmonitoring system inactive.	10/18/2024 High	On Hold
12/3/2024 Firmware rollback initiated unintentionallyclient device now stuck in bootloader loop.	12/12/2024 Low	Open
5/1/2024 Customer states predictive maintenance alert was missedpossible alert suppression rule.	5/2/2024 High	Closed - Resolved
4/26/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted.	5/3/2024 Medium	In Progress
1/8/2025 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken.	1/17/2025 Medium	Closed - Resolved
8/4/2024 Latest patch rolled out to wrong robot model familyrollback request submitted.	8/13/2024 Urgent	Closed
3/16/2025 Unable to reset robotic arm to home positionreset protocol fails at step 3.	3/26/2025 High	Cancelled
5/29/2024 Technician override mode triggering false alarmsUI miscommunication suspected.	5/30/2024 Medium	Closed
1/1/2025 Routine maintenance tag not updating in system despite completionworkflow integration error.	1/7/2025 High	In Progress
8/19/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	8/23/2024 Low	Cancelled
4/14/2025 Task scheduler running duplicate jobs on dual-robot configurationdeadlock conditions observed.	4/17/2025 High	On Hold
2/23/2025 Temperature sensor in robotic soldering unit reading above safe operating range.	2/27/2025 High	Closed - Resolved
8/18/2024 Automated welding arm intermittently halts during high-heat cyclessuspected sensor calibration drift.	8/21/2024 Urgent	Closed - Resolved
6/12/2024 Unexpected stop condition triggered during pallet rewrap routineinvestigating fault codes.	6/22/2024 Low	Open
6/1/2024 New actuator exhibiting slow response in colder environmentsmaterial tolerance concern.	6/9/2024 Medium	Closed - Resolved
9/20/2024 Customer service chatbot incorrectly routing requests about robotic arms to finance.	9/22/2024 Medium	Open
1/11/2025 Navigation system freezing mid-shiftpacket loss observed in Wi-Fi logs.	1/13/2025 Urgent	In Progress
9/12/2024 Mobile control app crashing after recent OS updatecompatibility fix required.	9/22/2024 High	On Hold
7/31/2024 Pick path optimization feature stuck in recalculating looplikely route matrix bug.	8/1/2024 Medium	Closed
3/27/2025 Support team reports double charge on robotic part restockSLA breach inquiry pending.	4/5/2025 Low	Closed - Resolved

7/17/2024 Customer reports excessive heat on robotics control panelcooling fan test requested.	7/22/2024 High	Cancelled
12/1/2024 Diagnostic tool unable to communicate with legacy hardwareadapter may be required.	12/10/2024 Medium	Closed - Resolved
5/21/2024 Error 412 triggered during over-the-air update to robotic welding units in Southeast territory.	5/26/2024 Urgent	Cancelled
11/4/2024 Billing dashboard showing duplicate line items for SLA renewalneeds manual reconciliation.	11/13/2024 Low	Open
4/21/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing.	4/28/2025 Medium	In Progress
10/27/2024 Product loader mistiming drop-off with downstream conveyorsync pulse missing.	11/4/2024 High	Closed - Resolved
3/28/2025 Night shift override not deactivating during scheduled switchlogic conflict in script.	3/30/2025 Medium	On Hold
8/16/2024 Return unit not accepting scanned QR codesoptical reader needs recalibration.	8/17/2024 High	Closed
5/29/2024 System audit flagging unauthorized access attempt on robotics control API.	5/29/2024 High	On Hold
9/10/2024 Support agent unable to replicate power cycling bug reported on new Roboweld Plus series.	9/17/2024 Medium	Closed
5/1/2024 Firmware rollback initiated unintentionallyclient device now stuck in bootloader loop.	5/6/2024 Urgent	Cancelled
10/1/2024 New actuator exhibiting slow response in colder environmentsmaterial tolerance concern.	10/2/2024 High	Open
10/30/2024 Automated welding arm intermittently halts during high-heat cyclessuspected sensor calibration drift.	11/4/2024 Medium	Closed - Resolved
10/7/2024 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	10/8/2024 Low	In Progress
5/30/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt.	6/2/2024 Medium	Closed - Resolved
10/8/2024 Customer reports robotic forklift overshooting dock alignment camera offset suspected.	10/8/2024 High	Open
12/30/2024 User permissions incorrectly assigned admin access granted to technician role.	1/2/2025 Low	Closed - Resolved
9/14/2024 Navigation system freezing mid-shiftpacket loss observed in Wi-Fi logs.	9/20/2024 High	In Progress
4/19/2025 Voice command module failing to recognize commands with headset mic input.	4/25/2025 Medium	Closed - Resolved
1/11/2025 Error 7002: No response from servo motor controller on axis Ypossible hardware failure.	1/19/2025 Urgent	Closed
4/27/2024 LED status indicator stuck in red despite system running normallyvisual false positive?	5/7/2024 Medium	Cancelled
8/20/2024 Customer service chatbot incorrectly routing requests about robotic arms to finance.	8/28/2024 High	On Hold
1/29/2025 Error 412 triggered during over-the-air update to robotic welding units in Southeast territory.	2/6/2025 Urgent	Closed - Resolved
11/9/2024 Remote shutdown of customer system initiated without proper command logpossible logging misfire.	11/12/2024 Low	Open
1/26/2025 Data not syncing across international locationstimezone setting discrepancies confirmed.	1/26/2025 Medium	Closed
5/8/2024 Latest patch rolled out to wrong robot model familyrollback request submitted.	5/8/2024 High	In Progress
8/22/2024 Technician override mode triggering false alarmsUI miscommunication suspected.	8/27/2024 Low	On Hold
1/23/2025 Unexpected stop condition triggered during pallet rewrap routineinvestigating fault codes.	1/25/2025 Medium	Closed - Resolved
7/18/2024 Night shift override not deactivating during scheduled switchlogic conflict in script.	7/23/2024 Urgent	Cancelled
8/29/2024 Billing dashboard showing duplicate line items for SLA renewalneeds manual reconciliation.	9/3/2024 High	On Hold
4/12/2025 Customer states predictive maintenance alert was missedpossible alert suppression rule.	4/21/2025 Medium	Closed
10/12/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing.	10/12/2024 High	Closed - Resolved
8/4/2024 Mobile control app crashing after recent OS updatecompatibility fix required.	8/12/2024 High	Cancelled
8/9/2024 Downtime incorrectly logged as resolved in dashboardresolution timestamp error.	8/11/2024 Urgent	Open

7/3/2024 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch.	7/8/2024 Medium	In Progress
1/25/2025 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken.	1/28/2025 Medium	Closed - Resolved
3/20/2025 Repeated '404 device not found' error on support dashboardbelieved to be ID mismatch.	3/23/2025 High	Cancelled
5/29/2024 Battery drain accelerating on self-navigating picker botsclient requests hardware review.	5/31/2024 Low	Closed - Resolved
1/15/2025 Pick path optimization feature stuck in recalculating looplikely route matrix bug.	1/19/2025 High	Open
11/13/2024 Customer unable to submit service ticket via mobile portalUI issue on latest Android version.	11/21/2024 Low	In Progress
8/24/2024 Support team reports double charge on robotic part restockSLA breach inquiry pending.	9/1/2024 High	On Hold
8/6/2024 Task scheduler running duplicate jobs on dual-robot configurationdeadlock conditions observed.	8/8/2024 Urgent	Closed
7/1/2024 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	7/10/2024 Medium	Closed - Resolved
10/14/2024 Motion sensor fault in entry-level AGVsuspected electromagnetic interference.	10/23/2024 Medium	Open
3/26/2025 Diagnostic tool unable to communicate with legacy hardwareadapter may be required.	3/30/2025 Urgent	Closed
8/2/2024 Scheduled maintenance scripts not executing on east region serverslikely time zone mismatch.	8/8/2024 Medium	In Progress
4/28/2024 HR database not syncing with shift handoff bot schedulermissing employee record.	5/4/2024 High	On Hold
7/16/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted.	7/19/2024 Low	Closed - Resolved
5/25/2024 Inconsistent barcode scanning during inbound sortationrequesting diagnostic logs.	6/2/2024 High	Cancelled
9/8/2024 Wireless module upgrade caused latency spikepossible firmware mismatch.	9/18/2024 Medium	Closed - Resolved
2/2/2025 Custom firmware deployment not stickingdevice reverts to factory version after reboot.	2/12/2025 Urgent	Closed - Resolved
7/23/2024 Unexpected motor vibration on high-speed units deployed in humid environments.	7/30/2024 Medium	Open
8/27/2024 Idle time tracking for warehouse units not logging correctlytelemetry data gap.	8/29/2024 Medium	In Progress
11/13/2024 AI co-pilot interface displaying outdated warehouse inventory despite live API integration.	11/16/2024 High	On Hold
9/30/2024 Product loader mistiming drop-off with downstream conveyorsync pulse missing.	10/8/2024 Low	Closed
4/1/2025 Unable to reset robotic arm to home positionreset protocol fails at step 3.	4/11/2025 High	Closed - Resolved
3/11/2025 Service report PDF not attaching to customer CRM recordautomation flow broken.	3/14/2025 High	Cancelled
12/3/2024 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions.	12/7/2024 Medium	Closed - Resolved
7/14/2024 Robot arm #4 failed precision test during QAtolerance exceeds threshold by 0.04 mm.	7/24/2024 High	Closed
5/2/2024 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	5/9/2024 Low	Cancelled
9/13/2024 Inventory report mislabeling robotics model numbersSKU logic misfire.	9/17/2024 Medium	On Hold
3/31/2025 Label printer on packing bot jamming intermittentlyhardware service request opened.	4/4/2025 Urgent	Open
4/17/2025 Armature alignment reset required after shippingrequesting field calibration.	4/26/2025 Medium	Closed - Resolved
12/28/2024 Issue syncing sales data from ERP into robotics supply chain dashboard.	1/3/2025 High	In Progress
11/16/2024 Overhead robotic crane misaligned after system updaterequesting recalibration walkthrough.	11/21/2024 Urgent	In Progress
11/14/2024 License expiration alerts not appearing for client adminmonitoring system inactive.	11/18/2024 Low	Closed - Resolved
7/24/2024 High-pitched tone coming from servo in model XR100engineering to review noise profile.	7/25/2024 Medium	On Hold
8/21/2024 Load cell in robotic lifter reading zero under active payloadsuspected cable break.	8/24/2024 High	Closed

4/14/2025 Return unit not accepting scanned QR codesoptical reader needs recalibration.	4/24/2025 Medium	Closed - Resolved
5/15/2024 Battery health metrics not populating in regional dashboardtelemetry stream missing.	5/17/2024 Medium	Cancelled
6/30/2024 Discrepancy between scanned and delivered SKUspotential robotic misclassification event.	7/9/2024 High	Open
8/19/2024 Routine maintenance tag not updating in system despite completionworkflow integration error.	8/28/2024 High	Cancelled
5/3/2024 Customer account flagged as inactive during quarterly synccontract still in force until Q4.	5/8/2024 Urgent	On Hold
10/12/2024 Customer reports excessive heat on robotics control panelcooling fan test requested.	10/13/2024 Low	Closed - Resolved
7/17/2024 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected.	7/21/2024 Medium	Closed - Resolved
6/23/2024 Client unable to archive closed support ticketspermission role misconfiguration.	6/26/2024 Medium	Open
10/8/2024 Temperature sensor in robotic soldering unit reading above safe operating range.	10/15/2024 High	Closed
11/27/2024 API returning null values for order tracking endpointbackend request timing out.	12/4/2024 Low	In Progress
1/15/2025 3D vision system under-picking SKUs from top shelvesimage recognition needs retraining.	1/20/2025 High	Closed - Resolved
8/7/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter.	8/16/2024 Urgent	On Hold
9/16/2024 Return unit not accepting scanned QR codesoptical reader needs recalibration.	9/24/2024 Medium	Closed
8/27/2024 System audit flagging unauthorized access attempt on robotics control API.	9/3/2024 High	Cancelled
11/4/2024 Picking robot skipping assigned aisle in optimization routemap index might be corrupted.	11/13/2024 Urgent	Open
10/30/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing.	10/31/2024 Low	Closed - Resolved
1/19/2025 Issue syncing sales data from ERP into robotics supply chain dashboard.	1/23/2025 Medium	In Progress
10/17/2024 Load cell in robotic lifter reading zero under active payloadsuspected cable break.	10/24/2024 High	Closed - Resolved
10/28/2024 Robot arm #4 failed precision test during QAtolerance exceeds threshold by 0.04 mm.	11/4/2024 High	Open
5/24/2024 Scheduled maintenance scripts not executing on east region serverslikely time zone mismatch.	5/30/2024 Low	In Progress
7/28/2024 Navigation system freezing mid-shiftpacket loss observed in Wi-Fi logs.	7/31/2024 High	On Hold
5/7/2024 Unexpected motor vibration on high-speed units deployed in humid environments.	5/8/2024 Medium	Closed
1/28/2025 Remote shutdown of customer system initiated without proper command logpossible logging misfire.	2/1/2025 Urgent	Closed - Resolved
9/1/2024 Routine maintenance tag not updating in system despite completionworkflow integration error.	9/8/2024 Medium	Cancelled
6/27/2024 Support team reports double charge on robotic part restockSLA breach inquiry pending.	7/2/2024 Medium	Closed - Resolved
9/15/2024 AI co-pilot interface displaying outdated warehouse inventory despite live API integration.	9/15/2024 High	In Progress
11/4/2024 License expiration alerts not appearing for client adminmonitoring system inactive.	11/9/2024 High	Closed - Resolved
2/6/2025 Unexpected stop condition triggered during pallet rewrap routineinvestigating fault codes.	2/6/2025 Urgent	On Hold
6/4/2024 Night shift override not deactivating during scheduled switchlogic conflict in script.	6/10/2024 Low	Closed
1/2/2025 API returning null values for order tracking endpointbackend request timing out.	1/4/2025 Medium	Cancelled
10/22/2024 HR database not syncing with shift handoff bot schedulermissing employee record.	10/22/2024 High	Open
7/5/2024 Support agent unable to replicate power cycling bug reported on new Roboweld Plus series.	7/14/2024 Medium	Closed
12/11/2024 Downtime incorrectly logged as resolved in dashboardresolution timestamp error.	12/17/2024 Urgent	Cancelled
7/29/2024 Customer reports excessive heat on robotics control panelcooling fan test requested.	8/7/2024 High	On Hold

9/13/2024 High-pitched tone coming from servo in model XR100engineering to review noise profile.	9/20/2024 Medium	Open
8/11/2024 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt.	8/13/2024 Low	Closed - Resolved
1/19/2025 Heat map of robotic traffic not loading for West Coast territoryvisualization component broken.	1/22/2025 Medium	In Progress
2/17/2025 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions.	2/18/2025 Urgent	Closed - Resolved
5/21/2024 Wireless module upgrade caused latency spikepossible firmware mismatch.	5/21/2024 High	Closed
2/2/2025 Voice command module failing to recognize commands with headset mic input.	2/4/2025 Medium	Closed - Resolved
11/14/2024 Inconsistent barcode scanning during inbound sortation requesting diagnostic logs.	11/20/2024 High	Cancelled
9/11/2024 3D vision system under-picking SKUs from top shelvesimage recognition needs retraining.	9/16/2024 Low	Closed - Resolved
3/24/2025 Overhead robotic crane misaligned after system updaterequesting recalibration walkthrough.	4/1/2025 Low	Open
8/9/2024 Data not syncing across international locationstimezone setting discrepancies confirmed.	8/13/2024 Medium	In Progress
6/18/2024 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	6/28/2024 Medium	On Hold
8/18/2024 Diagnostic tool unable to communicate with legacy hardwareadapter may be required.	8/20/2024 High	Cancelled
6/14/2024 New actuator exhibiting slow response in colder environmentsmaterial tolerance concern.	6/21/2024 High	Open
9/18/2024 Technician override mode triggering false alarmsUI miscommunication suspected.	9/20/2024 Urgent	In Progress
7/7/2024 Label printer on packing bot jamming intermittentlyhardware service request opened.	7/16/2024 Low	Closed - Resolved
8/20/2024 Product loader mistiming drop-off with downstream conveyorsync pulse missing.	8/23/2024 High	On Hold
9/1/2024 Temperature-controlled arm not holding cold-pack products steadilyactuator lag suspected.	9/10/2024 Medium	Closed
7/22/2024 Customer account flagged as inactive during quarterly synccontract still in force until Q4.	7/25/2024 Urgent	Closed - Resolved
2/6/2025 Temperature sensor in robotic soldering unit reading above safe operating range.	2/11/2025 Medium	Closed - Resolved
12/26/2024 Customer service chatbot incorrectly routing requests about robotic arms to finance.	1/4/2025 High	Closed - Resolved
8/6/2024 Client unable to archive closed support ticketspermission role misconfiguration.	8/8/2024 Medium	Closed
11/24/2024 Mobile control app crashing after recent OS updatecompatibility fix required.	11/29/2024 High	In Progress
11/26/2024 Automated welding arm intermittently halts during high-heat cyclessuspected sensor calibration drift.	12/1/2024 High	Cancelled
2/21/2025 Battery health metrics not populating in regional dashboardtelemetry stream missing.	2/27/2025 Urgent	On Hold
6/4/2024 Discrepancy between scanned and delivered SKUspotential robotic misclassification event.	6/13/2024 Low	Open
11/20/2024 Pick path optimization feature stuck in recalculating looplikely route matrix bug.	11/20/2024 Medium	Cancelled
4/26/2024 Error 7002: No response from servo motor controller on axis Ypossible hardware failure.	4/29/2024 High	On Hold
7/6/2024 Error 412 triggered during over-the-air update to robotic welding units in Southeast territory.	7/10/2024 Medium	Open
12/3/2024 LED status indicator stuck in red despite system running normallyvisual false positive?	12/11/2024 High	Closed - Resolved
4/14/2025 Billing dashboard showing duplicate line items for SLA renewalneeds manual reconciliation.	4/19/2025 Low	Closed - Resolved
4/28/2024 Firmware rollback initiated unintentionallyclient device now stuck in bootloader loop.	5/2/2024 Medium	Closed
7/31/2024 Customer unable to submit service ticket via mobile portalUI issue on latest Android version.	8/7/2024 Urgent	In Progress
2/10/2025 Custom firmware deployment not stickingdevice reverts to factory version after reboot.	2/18/2025 High	Closed - Resolved
11/6/2024 Idle time tracking for warehouse units not logging correctlytelemetry data gap.	11/12/2024 Medium	Closed

2/10/2025 Unable to reset robotic arm to home positionreset protocol fails at step 3.	2/13/2025 Low	Cancelled
2/3/2025 Battery drain accelerating on self-navigating picker botsclient requests hardware review.	2/4/2025 High	On Hold
11/11/2024 User permissions incorrectly assigned admin access granted to technician role.	11/20/2024 Medium	Open
10/22/2024 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	10/28/2024 Urgent	Closed - Resolved
10/26/2024 Customer states predictive maintenance alert was missedpossible alert suppression rule.	10/30/2024 Urgent	In Progress
12/21/2024 Inventory report mislabeling robotics model numbersSKU logic misfire.	12/22/2024 Low	Closed - Resolved
1/8/2025 Order #98234 missing firmware version 5.3 for XYZ Series actuatorrequires urgent patch.	1/14/2025 Medium	Closed
9/28/2024 Armature alignment reset required after shipping requesting field calibration.	10/1/2024 High	In Progress
4/15/2025 Customer reports robotic forklift overshooting dock alignment camera offset suspected.	4/25/2025 Medium	Cancelled
11/15/2024 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	11/23/2024 High	On Hold
3/18/2025 Task scheduler running duplicate jobs on dual-robot configurationdeadlock conditions observed.	3/26/2025 Medium	Open
2/8/2025 Latest patch rolled out to wrong robot model familyrollback request submitted.	2/10/2025 Medium	Closed - Resolved
11/10/2024 Repeated '404 device not found' error on support dashboardbelieved to be ID mismatch.	11/10/2024 High	On Hold
10/10/2024 Delivery tracking API pushing duplicate status updatescausing client-side UI clutter.	10/12/2024 High	Closed
6/16/2024 Service report PDF not attaching to customer CRM recordautomation flow broken.	6/20/2024 Urgent	Closed - Resolved
3/31/2025 Motion sensor fault in entry-level AGVsuspected electromagnetic interference.	4/3/2025 Low	Cancelled
9/15/2024 Load cell in robotic lifter reading zero under active payloadsuspected cable break.	9/24/2024 Urgent	Open
11/24/2024 Customer states predictive maintenance alert was missedpossible alert suppression rule.	11/25/2024 Low	In Progress
7/26/2024 Task scheduler running duplicate jobs on dual-robot configurationdeadlock conditions observed.	7/30/2024 Medium	Closed - Resolved
12/17/2024 Autonomous floor units reporting repeated LIDAR misreads in low-light conditions.	12/24/2024 High	Closed
11/12/2024 Data not syncing across international locationstimezone setting discrepancies confirmed.	11/13/2024 Medium	Closed - Resolved
6/4/2024 Billing dashboard showing duplicate line items for SLA renewalneeds manual reconciliation.	6/6/2024 High	Cancelled
8/9/2024 Scheduled maintenance scripts not executing on east region serverslikely time zone mismatch.	8/16/2024 Medium	Closed - Resolved
9/21/2024 Customer reports robotic forklift overshooting dock alignmentcamera offset suspected.	9/22/2024 Urgent	Open
5/24/2024 Unable to reset robotic arm to home positionreset protocol fails at step 3.	5/26/2024 High	In Progress
1/29/2025 Error 7002: No response from servo motor controller on axis Ypossible hardware failure.	2/5/2025 Medium	On Hold
1/24/2025 Customer reports excessive heat on robotics control panelcooling fan test requested.	1/28/2025 High	Closed
6/5/2024 License expiration alerts not appearing for client adminmonitoring system inactive.	6/13/2024 Low	In Progress
1/24/2025 System audit flagging unauthorized access attempt on robotics control API.	2/2/2025 Urgent	Cancelled
12/11/2024 New actuator exhibiting slow response in colder environmentsmaterial tolerance concern.	12/14/2024 High	On Hold
7/23/2024 LED status indicator stuck in red despite system running normallyvisual false positive?	7/25/2024 Medium	Closed - Resolved
5/9/2024 Voice command module failing to recognize commands with headset mic input.	5/15/2024 Low	Closed - Resolved
1/21/2025 Robot arm #4 failed precision test during QAtolerance exceeds threshold by 0.04 mm.	1/24/2025 High	Open
6/21/2024 Diagnostic tool unable to communicate with legacy hardwareadapter may be required.	6/27/2024 Medium	Closed

7/21/2024 Customer unable to submit service ticket via mobile portalUI issue on latest Android version.	7/24/2024 Urgent	In Progress
3/5/2025 Label printer on packing bot jamming intermittentlyhardware service request opened.	3/8/2025 Low	Cancelled
6/12/2024 Client unable to archive closed support ticketspermission role misconfiguration.	6/12/2024 Medium	On Hold
7/11/2024 Error 412 triggered during over-the-air update to robotic welding units in Southeast territory.	7/11/2024 Medium	Open
8/11/2024 Discrepancy between scanned and delivered SKUspotential robotic misclassification event.	8/18/2024 High	Closed - Resolved
12/3/2024 Support agent unable to replicate power cycling bug reported on new Roboweld Plus series.	12/6/2024 High	Closed - Resolved
7/24/2024 Idle time tracking for warehouse units not logging correctlytelemetry data gap.	8/3/2024 High	Closed
5/27/2024 AI co-pilot interface displaying outdated warehouse inventory despite live API integration.	5/31/2024 Urgent	Closed - Resolved
3/11/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	3/13/2025 Low	Cancelled
12/24/2024 Technician override mode triggering false alarmsUI miscommunication suspected.	1/2/2025 Medium	Closed - Resolved
10/11/2024 User permissions incorrectly assigned admin access granted to technician role.	10/12/2024 Medium	Open
4/17/2025 Downtime incorrectly logged as resolved in dashboardresolution timestamp error.	4/24/2025 High	In Progress
2/14/2025 Automated welding arm intermittently halts during high-heat cyclessuspected sensor calibration drift.	2/17/2025 Medium	On Hold
6/7/2024 Firmware rollback initiated unintentionallyclient device now stuck in bootloader loop.	6/15/2024 Medium	On Hold
8/29/2024 Routine maintenance tag not updating in system despite completionworkflow integration error.	9/3/2024 High	Open
11/3/2024 Inventory report mislabeling robotics model numbersSKU logic misfire.	11/11/2024 High	Closed - Resolved
9/22/2024 Battery health metrics not populating in regional dashboardtelemetry stream missing.	9/30/2024 Urgent	In Progress
1/25/2025 Support team reports double charge on robotic part restockSLA breach inquiry pending.	1/29/2025 Low	Closed - Resolved
12/27/2024 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	12/31/2024 Medium	Closed
4/23/2024 Unexpected motor vibration on high-speed units deployed in humid environments.	4/24/2024 High	Cancelled
4/2/2025 Temperature sensor in robotic soldering unit reading above safe operating range.	4/4/2025 Urgent	In Progress
1/5/2025 Motion sensor fault in entry-level AGVsuspected electromagnetic interference.	1/7/2025 Low	On Hold
7/18/2024 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	7/28/2024 Medium	Closed - Resolved
1/5/2025 Unexpected stop condition triggered during pallet rewrap routineinvestigating fault codes.	1/10/2025 High	Cancelled
10/15/2024 Customer unable to access remote diagnostics via mobile portalauthentication token not refreshing.	10/25/2024 High	Closed - Resolved
2/10/2025 Repeated '404 device not found' error on support dashboardbelieved to be ID mismatch.	2/15/2025 High	Open
6/1/2024 Remote shutdown of customer system initiated without proper command logpossible logging misfire.	6/10/2024 Urgent	Closed
4/1/2025 Customer service chatbot incorrectly routing requests about robotic arms to finance.	4/6/2025 Low	Closed - Resolved
3/23/2025 Inconsistent barcode scanning during inbound sortationrequesting diagnostic logs.	3/23/2025 Medium	In Progress
9/22/2024 Latest patch rolled out to wrong robot model familyrollback request submitted.	9/22/2024 Medium	Closed - Resolved
7/15/2024 API returning null values for order tracking endpointbackend request timing out.	7/18/2024 High	In Progress
10/7/2024 Wireless module upgrade caused latency spikepossible firmware mismatch.	10/7/2024 Urgent	On Hold
7/4/2024 3D vision system under-picking SKUs from top shelvesimage recognition needs retraining.	7/5/2024 Low	Closed - Resolved
3/4/2025 Picking robot skipping assigned aisle in optimization routemap index might be corrupted.	3/7/2025 Medium	Cancelled

12/27/2024 Overhead robotic crane misaligned after system updaterequesting recalibration walkthrough.	1/2/2025 Medium	Closed - Resolved
4/18/2025 HR database not syncing with shift handoff bot schedulermissing employee record.	4/23/2025 High	Open
4/8/2025 Product loader mistiming drop-off with downstream conveyorsync pulse missing.	4/13/2025 Urgent	Closed - Resolved
6/11/2024 High-pitched tone coming from servo in model XR100engineering to review noise profile.	6/14/2024 Low	In Progress
7/22/2024 Night shift override not deactivating during scheduled switchlogic conflict in script.	7/30/2024 Medium	Closed - Resolved
2/12/2025 Feedback loop delay causing robotic palletizer to miss timing sync with conveyor belt.	2/12/2025 High	Closed
1/28/2025 Navigation system freezing mid-shiftpacket loss observed in Wi-Fi logs.	2/1/2025 Medium	Cancelled
2/6/2025 Suction cup gripper losing pressure after 12 cyclescheck vacuum seal integrity.	2/8/2025 High	On Hold
5/2/2024 Excessive noise reported from robotic jointscustomer suspects lubrication schedule not syncing.	5/12/2024 Medium	In Progress
5/1/2024 Assembly line pauses when robotic gripper fails to complete handofflog shows force threshold error.	5/9/2024 Urgent	On Hold
3/5/2025 Technician override mode triggering false alarmsUI miscommunication suspected.	3/9/2025 Medium	Closed - Resolved