





force-shear Ets/Ec=0.08 shear Vy=Vz=0.50 2s
force-shear Ets/Ec=0.08 shear Vy=Vz=1.00 2s
force-shear Ets/Ec=0.08 shear Vy=Vz=1.50 2s
force-shear Ets/Ec=0.08 shear Vy=Vz=2.00 2s
force-shear Ets/Ec=0.08 shear Vy=Vz=4.00 2s



force-shear Ets/Ec=0.08 shear Vy=Vz=0.50 2s
force-shear Ets/Ec=0.08 shear Vy=Vz=1.00 2s
force-shear Ets/Ec=0.08 shear Vy=Vz=1.50 2s
force-shear Ets/Ec=0.08 shear Vy=Vz=2.00 2s
force-shear Ets/Ec=0.08 shear Vy=Vz=4.00 2s