

Replacement Limit Switch

It doesn't happen very often, but occasionally a limit switch can be broken during assembly or transport. Search our website for "switch". SKU: 26181