

A5 Slave IF JUMPER A6 Slave IF JUMPER A7 Slave IF JUMPER SCL1 I2C Slave - SCL SDA1 I2C Slave - SDA

**13 LED** 

10 SPI Master / Slave - SSel

9 GPIO - Trigger

8 GPIO - Test in

7 GPIO - Test out

6 GPIO - Test in

4 SWD Master – Data 3 SWD Master – SWCLK

1 UART Slave – USB2UART 0 UART Slave – USB2UART

> 14 HDQ Master 15 HDQ Master

16 USART Master

17 USART Master 18 USART Slave

19 USART Slave

21 I2C Master – SCL

20 I2C Master – SDA