





A Telemeter may be necessary to measure the volume of the room for disinfection or insect removal.

It gives precise measurements with a laser beam to evaluate lengths accurately. The area and volume function is used to calculate the dimensions of a room.

Max. measuring range: 20 m

## **REFERENCE**

	REFERENCE
TELEMETER	3010.601

## **DIMENSIONS**

