

PULSE CHECK REPORT

1. ROOM SUBMISSION

Students perform room checked for **total 430 times** from September 2025 to January 2026

BUILDING	SUBMISSION
DSB	5
BRC	5
LSC	154
FRIE	47
IRC	57
KPAV	47
DETW	18
DMCBH	96

BUILDING CODE	YEAR	MONTH	SUBMISSION COUNTS
BRC	2025	August	1
BRC	2025	September	1
BRC	2025	November	2
BRC	2025	December	1
DETW	2025	September	1
DETW	2025	October	6
DETW	2025	November	6
DETW	2025	December	4
DETW	2026	January	1
DMCBH	2025	September	20
DMCBH	2025	October	35
DMCBH	2025	November	20
DMCBH	2025	December	15
DMCBH	2026	January	6
DSB	2025	September	2
DSB	2025	October	1
DSB	2025	November	2
FRIE	2025	September	13
FRIE	2025	October	16
FRIE	2025	November	13
FRIE	2025	December	4
FRIE	2026	January	1
IRC	2025	September	20
IRC	2025	October	20
IRC	2025	November	6
IRC	2025	December	7
IRC	2026	January	4
KPAV	2025	September	11
KPAV	2025	October	17

2. ISSUES DISCOVERED

Students perform discovered **total 64 issues** from September 2025 to January 2026

BUILDING	FLAGS
BRC	3
FRIE	12
LSC	21
KPAV	9
IRC	3
DETW	4
DMCBH	11
MEDC	1

BUILDING CODE	YEAR	MONTH	SUBMISSION COUNTS
BRC	2025	September	1
BRC	2025	November	1
BRC	2025	December	1
DETW	2025	October	2
DETW	2025	December	2
DMCBH	2025	September	1
DMCBH	2025	October	1
DMCBH	2025	November	4
DMCBH	2025	December	5
FRIE	2025	September	4
FRIE	2025	October	1
FRIE	2025	November	3
FRIE	2025	December	4
IRC	2025	September	2
IRC	2025	December	1
KPAV	2025	September	1
KPAV	2025	October	5
KPAV	2025	November	3
LSC	2025	September	6
LSC	2025	October	5
LSC	2025	November	8
LSC	2025	December	2
MEDC	2025	December	1

3. Maintenance Check

Students discovered **7 issues** during the Crestron-Zoom and Small Seminar Room Check

BUILDING CODE	YEAR	MONTH	ISSUES	DESCRIPTIONS
BRC	2025	November	1	BRC 351 maintenance check: Lectern PC cannot log in (FOM Instructor password expired)
DMCBH	2025	November	1	Lectern mic has to be on for the active audience mic to be showed on the projector screen.
FRIE	2025	November	2	The lights need to be replaced, some of them are really dim. Sound was a bit muffled at the lectern PC spot. Reminder to bring the new battery with label back.
KPAV	2025	November	1	Missing wireless mouse + slide advancer
LSC	2025	November	2	LT2: mic 61 and 62 muffled sound; mic 31 button is jammed (cannot be pressed). Burnt out lights: 1 spotlight (on the right)

BUILDING CODE	YEAR	MONTH	FLAG	DESCRIPTIONS
DETW	2025	December	1	The IP camera doesn't have the label
DMCBH	2025	December	2	On Zoom + Teams: neat bar microphones does not work
IRC	2025	December	1	1 burnout light on the ceiling.
LSC	2025	December	2	No labels on HDMI
MEDC	2025	December	1	Missing adapter for HDMI