skkmigas PERTAMINA EP	**PERTAMINA EP REGIONAL 1 ZONA 4**	POG

DATASHEET – SAFETY SIGN AND EQUIPMENT	No. Dok. : TMBP-SP001-PS-DST-D105 Rev. : A Halaman : 1 dari 4

NAMA PEMILIK PROYEK : **PT PERTAMINA EP**

NAMA PROYEK : **JASA PEMBANGUNAN FASILITAS PRODUKSI STASIUN PENGUMPUL (SP) TANJUNG MIRING BARAT & KARANGAN TIMUR**

LOKASI : **SP TANJUNG MIRING BARAT & KARANG TIMUR - FIELD LIMAU**

NO. KONTRAK : **SA02035383B**

A	24-12-25	Issued For Review	NA	AS	RTN		
REV.	TGL.	DESKRIPSI	DISIAPKAN	DIPERIKSA	DISETUJUI	DIPERIKSA	DISETUJUI
			PT. PROSYMPAC OIL & GAS			PT. PERTAMINA EP	

TABEL REVISI

Rev.	Tanggal	Deskripsi

COMMENT RESPONSE SHEET

No.	Page	Company's Comment	Contractor's Response	Remarks

PGG	JASA PEMBANGUNAN FASILITAS PRODUKSI STASIUN PENGUMPUL (SP) TANJUNG MIRING BARAT & KARANGAN TIMUR	Doc. No: TMBP-SP001-PS-DST-D105
		PAGE 1 of 1
		Date: 24-Dec-25

DATASHEET - SAFETY SIGN AND EQUIPMENT

1. General Information

Standard	:	ANSI Z535, ISO 3864, OSHA 1910.144

2. Design Data

Materuak	:	Suitable for tropical land environment
Outdoor Material Requirement	:	- The base shall be galvanized plate
		- High intensity reflective and weather proof material for sign color and pictograms/symbol or text
Indoor Material Requirement	:	- Sign printed on self-adhesive polymer plastics with permanent adhesive
		- Sign printed on plastic (minimum 2 mm of thick)
Mounting	:	Stainless steel (type 316) mounting brackets and bolts and nuts shall be supplied for all sign and name plates
Luminance	:	Min. 100/10 mcd/m^2 (after 10 and 60 min) DIN 65710 requires 20/2.8 mcd/m^2
Thickness	:	Approx. 0.35 mm
Weight	:	Approx 500 g/m^2
Marking	:	- Bahasa Indonesia and English
		- Sign shall be shown on both side for outdoor emergency escape sign

3. Safety Sign Requirement

SS	Description	Qty
SS1	Safety Sign: Primary Muster Point	1
SS2	Safety Sign: Secondary Muster Po	1
SS3	Safety Sign: Dry Chemical Portabl	25
SS4	Safety Sign: Portable CO2 Fire Ext	5
SS5	Safety Sign: Safety Shower and Ey	2
SS6	Safety Sign: Portable Eyewash Sta	2
SS7	Safety Sign: High Noise Area & He	3
SS8	Safety Sign: Chemical Storage Are	3
SS9	Safety Sign: First Aid Kit	2
SS10	Safety Sign: Exit (Right Sign)	20
SS11	Safety Sign: Exit (Left Sign)	20
SS12	Safety Sign: (No Smoking ARea)	5
SS13	Safety Sign:(PPE Required)	5

4. DRAWING