

A: Precision (SQI>0 for 39% of weights)
B: Machined metal (SQI>0 for 42% of weights)
C: High-value module (SQI>0 for 18% of weights)
Sub-indicator, B3 vs L0
1.0
0.5
0.0
−0.5
−1.0
S_M material
S_E energy
S_C carbon
S_H workload