

Patrick Martino Site Vice President, Vogtle Unit 3 7825 River Road Waynesboro, Georgia 30830 706 848 6602 tel

March 14, 2023

ND-23-0140

Docket No.: 52-025

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Southern Nuclear Operating Company

Vogtle Electric Generating Plant (VEGP) – Unit 3

Licensee Event Report 2023-001-00

Manual Actuation of Reactor Protection System During Mode 3 Due to an Inadequate

Procedure Step

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv)(A), Southern Nuclear Operating Company is submitting the enclosed Licensee Event Report for VEGP Unit 3.

This letter contains no regulatory commitments. If you have questions regarding the enclosed information, please contact Will Garrett at (706) 848-7154.

Respectfully submitted,

Patrick A. Martino

Site Vice President, Unit 3

PAM/KMS/sfr

Enclosure:

Unit 3 Licensee Event Report 2023-001-00

CC:

Regional Administrator, Region II

VPO Project Manager

Senior Resident Inspector - Vogtle 3 & 4

Director, Environmental Protection Division - State of Georgia

Vogtle Electric Generating Plant - Unit 3

Licensee Event Report 2023-001-00

Manual Actuation of Reactor Protection System During Mode 3 Due to an Inadequate Procedure Step

Enclosure

Unit 3 Licensee Event Report 2023-001-00

NRC FORM 366 (01-10-2023)

U.S. NUCLEAR REGULATORY COMMISSION

PPROVED	BY OMB:	NO.	3150-0104
---------	---------	-----	-----------

EXPIRES: 12/31/2023

AND SECURITY OF THE SECURITY O

LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/) Estimated burden per response to comply with this mandatory collection request 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 Af0M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-9001, or by email to Infooelects, Resource@nnc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street MW, Washington, DC 20503; email: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

								rec	questing	g or requiring th	e collection	n displays a currently	valid OMB control n	umber.			
Facility Name Vogtle Electric Generating Plant, Unit 3							050 2. Docket Num			ocket Number		3. Pag	age				
								052		00025		1	OF	2			
4. Title									_		1						
Manua	I Actuat	ion of Re	actor Pr	rotection Sys	tem Dur	ing Mode	9 3 D	ue to ar	n In	adequa	te Pro	ocedure St	ер				
5.	5. Event Date 6. LER Number 7. Report Date							t Date	ate 8. Other Facilities Involved								
Month	Day	Year	Year	Sequential Number	Revision No.	Month [Day Year		Facility Name				050	Docket Number		
01	14	2023	2023	- 001 -	00	03	14	202	23	Facility Na	y Name			052	52 Docket Num		
9. Operati	ing Mode		3	3			1	10. Power	Leve	el .		000					
			11. This F	Report is Subn	nitted Pur	suant to th	ne Rec	uiremen	its of	f 10 CFR	§: (CI	heck all that	apply)				
10 C	10 CFR Part 20 20.2203(a)(2)(vi)				10 C	10 CFR Part 50			50.73(a)(2)(ii)(A)			50.73(a)(2)(viii)(A)			73.1	200(a)	
20.	20.2201(b) 20.2203(a)(3)(i)			.03(a)(3)(i)	50	50.36(c)(1)(i)(A)			50.73(a)(2)(ii)(B)			50.73(a)(2)(viii)(B)			73.1200(b)		
20.	20.2201(d) 20.2203(a)(3)(ii)			.03(a)(3)(ii)	50.36(c)(1)(ii)(A)			50.73(a)(2)(iii)			50.73(a)(2)(ix)(A)			73.1200(c)			
20.	20.2203(a)(1) 20.2203(a)(4)			:03(a)(4)	50.36(c)(2)			V 5	50.73(a)(2)(iv)(A)			50.73(a)(2)(x)			73.1200(d)		
20.	20.2203(a)(2)(i) 10 CFR Part 21			R Part 21	50.46(a)(3)(ii)			5	50.73(a)(2)(v)(A) 10 CFI			10 CFR	Part 73 73.1200(e)				
20.	20.2203(a)(2)(ii) 21.2(c)			50.69(g)			5	50.73(a)(2)(v)(B)			73.77(a)(1)		73.1200(f)			
20.	20.2203(a)(2)(iii)			50.73(a)(2)(i)(A)			50.73(a)(2)(v)(C)			C)	73.77(a)(2)(i)			73.1	200(g)		
20.	20.2203(a)(2)(iv)			50.73(a)(2)(i)(B)			50.73(a)(2)(v)(D) 73.77(a			a)(2)(ii)	a)(2)(ii) 73.1200(h)						
20.	.2203(a)(2	2)(v)			50	.73(a)(2)(i)((C)	5	50.73	(a)(2)(vii)						
ОТ	HER (Spe	ecify here,	in abstract	t, or NRC 366A).												
					12	. Licensee	Conta	act for th	iis Li	ER							
Will Ga		VEGP 38	k4 Licen	sing Manag	ger								Phone Nu	mber (In 70684			
				13. Complete (One Line f	for each Co	ompor	nent Fail	ure l	Describe	d in th	is Report					
Cause	,	System	Compon	nent Manufact	urer Repo	ortable to IRI	IS	Caus	e	Syst	tem	Componen	t Manufac	turer	Reporta	able to IRIS	
		14.	Suppleme	ental Report Expe	ected			_	_		-		Month	D	ay	Year	
No Yes (If yes, complete 15. Expect					1000				15. Expected Submission Date								
				roximately 13 sing					-								
				ST with Vog													

On January 14, 2023, at 0721 EST with Vogtle Electric Generating Plant (VEGP) Unit 3 in Mode 3 at 0 percent power, the Reactor Protection System (RPS) was manually actuated while conducting pre-criticality testing. The manual RPS actuation was in response to low gland steam pressure. The reactor trip breakers were in an open state prior to the RPS actuation. The cause of this event was an inadequate procedure step. This step was revised to require checking reactor trip breakers are not open prior to manually tripping the reactor in response to gland steam pressure below the procedural limit. This event is reportable under 10 CFR 50.73(a)(2)(iv)(A) as a condition that resulted in manual actuation of the RPS. VEGP Units 1, 2, and 4 were unaffected by this event.

NRC FORM 366A (01-10-2023)

U.S. NUCLEAR REGULATORY COMMISSION

ICENSEE EVENT REPORT (LER)



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)

APPROVED BY OMB: NO. 3150-0104 EXPIRES: 12/31/2023

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send commensite regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME		2. DOCKET NUMBER	3. LER NUMBER						
	050	00025	YEAR	SEQUENTIA NUMBER			REV NO.		
Vogtle Electric Generating Plant, Unit 3	052		2023	-	001	-[00		

NARRATIVE

EVENT DESCRIPTION

On January 14, 2023, at 0721 EST with Vogtle Electric Generating Plant (VEGP) Unit 3 in Mode 3 at 0 percent power, the Reactor Protection System (RPS) [EIIS: JC] was manually actuated. A gland steam system [EIIS: TC] pressure transient occurred during pre-criticality testing. Operators responded in accordance with the applicable Abnormal Operating Procedure (AOP) 3-AOP-202, "Condensate System Malfunctions," which required initiation of a manual reactor trip. There were no structures, systems or components that were out of service at the beginning of the event that contributed to the event. This event is reportable under 10 CFR 50.73(a)(2)(iv)(A) as a condition that resulted in manual actuation of the RPS.

EVENT CAUSE ANALYSIS

The cause of this event was determined to be an inadequate procedure step. The procedure 3-AOP-202 required a manual actuation of the RPS, when responding to low gland steam pressure, without first checking status of the reactor trip breakers. Since the reactor trip breakers were already open, the procedurally directed reactor trip was an unnecessary RPS actuation.

REPORTABILITY AND SAFETY ASSESSMENT

This event is reportable pursuant to 10 CFR 50.73(a)(2)(iv)(A) due to manual actuation of the RPS. There were no safety consequences due to this event. When the reactor was manually tripped, the reactor trip breakers were already in an open state, there was no irradiated fuel in the core, and there was no decay heat present. VEGP Units 1, 2, and 4 were unaffected by this event.

CORRECTIVE ACTIONS

Procedure 3-AOP-202, "Condensate System Malfunctions," was revised to require checking reactor trip breakers are not open prior to manually tripping the reactor when responding to gland steam pressure below the AOP's established limit.

PREVIOUS SIMILAR EVENTS

None