



Entergy Operations, Inc.
P.O. Box 756
Port Gibson, Mississippi 39150

Jeffery A. Hardy
Manager Regulatory Assurance
Grand Gulf Nuclear Station
Tel: 802-380-5124

10 CFR 50.73

GNRO2025-00015

May 13, 2025

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

SUBJECT: Grand Gulf Nuclear Station, Unit 1 Licensee Event Report 2025-002-00,
Automatic Emergency Diesel Generator Actuation Caused by Grid
Transient

Grand Gulf Nuclear Station, Unit 1
Docket No. 50-416
Renewed License No. NPF-29

Attached is Licensee Event Report (LER) 2025-002-00, Automatic Emergency Diesel Generator Actuation Caused by Grid Transient. This report is being submitted in accordance with 10 CFR 50.73(a)(2)(iv)(A), for any event that resulted in automatic actuation of an emergency diesel generator.

This letter contains no new Regulatory Commitments. Should you have any questions concerning the content of this letter, please contact me at 802-380-5124.

Sincerely,

A handwritten signature in blue ink, appearing to read "JA Hardy", with a stylized flourish at the end.

JAH/saw

Attachments: Licensee Event Report 2025-002-00

cc: NRC Senior Resident Inspector
Grand Gulf Nuclear Station
Port Gibson, MS 39150

U.S Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Attachment
Licensee Event Report 2025-002-00

NRC FORM 366 (04-02-2024)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB: NO. 3150-0104		EXPIRES: 04/30/2027			
		LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block) (See NUREG-1022, R.3 for instruction and guidance for completing this form https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)		Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov , and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.					
1. Facility Name Grand Gulf Nuclear Station, Unit 1		☒ 050 ☐ 052		2. Docket Number 00416		3. Page 1 of 2			
4. Title Automatic Emergency Diesel Generator Actuation Caused by Grid Transient									
5. Event Date			6. LER Number			7. Report Date		8. Other Facilities Involved	
Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name N/A ☐ 050 Docket Number
03	15	2025	2025	002	00	05	13	2025	Facility Name N/A ☐ 052 Docket Number
9. Operating Mode 1					10. Power Level 84				
11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)									
10 CFR Part 20		☐ 20.2203(a)(2)(vi)		10 CFR Part 50		☐ 50.73(a)(2)(ii)(A)		☐ 50.73(a)(2)(viii)(A)	
☐ 20.2201(b)		☐ 20.2203(a)(3)(i)		☐ 50.36(c)(1)(i)(A)		☐ 50.73(a)(2)(ii)(B)		☐ 50.73(a)(2)(viii)(B)	
☐ 20.2201(d)		☐ 20.2203(a)(3)(ii)		☐ 50.36(c)(1)(ii)(A)		☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)	
☐ 20.2203(a)(1)		☐ 20.2203(a)(4)		☐ 50.36(c)(2)		☒ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)	
☐ 20.2203(a)(2)(i)		10 CFR Part 21		☐ 50.46(a)(3)(ii)		☐ 50.73(a)(2)(v)(A)		10 CFR Part 73	
☐ 20.2203(a)(2)(ii)		☐ 21.2(c)		☐ 50.69(g)		☐ 50.73(a)(2)(v)(B)		☐ 73.77(a)(1)(i)	
☐ 20.2203(a)(2)(iii)				☐ 50.73(a)(2)(i)(A)		☐ 50.73(a)(2)(v)(C)		☐ 73.77(a)(2)(i)	
☐ 20.2203(a)(2)(iv)				☐ 50.73(a)(2)(i)(B)		☐ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(ii)	
☐ 20.2203(a)(2)(v)				☐ 50.73(a)(2)(i)(C)		☐ 50.73(a)(2)(vii)			
☐ Other (Specify here, in abstract, or in NRC 366A).									
12. Licensee Contact for this LER									
Licensee Contact Jeff Hardy, Regulatory Assurance Manager							Phone Number (Include Area Code) 802-380-5124		
13. Complete One Line for each Component Failure Described in this Report									
Cause	System	Component	Manufacturer	Reportable To IRIS	Cause	System	Component	Manufacturer	Reportable To IRIS
				N					
14. Supplemental Report Expected							15. Expected Submission Date		
☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)							Month	Day	Year
16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)									
On March 15, 2025, Grand Gulf Nuclear Station (GGNS), Unit 1 was in MODE 1 at 100 percent power with all safety systems operable. At 12:48 CDT, a grid transient caused the 17AC breaker to trip open. In response, the division III emergency diesel generator automatically started and repowered the 17AC safety-related electrical bus as designed. The grid transient was caused by degraded voltage of the offsite grid. The 17AC breaker was successfully closed after the grid transient with no further issues. No other safety systems actuated, and no radiological release occurred. All remaining offsite power sources remained energized. This report is being made in accordance with 10 CFR 50.73(a)(2)(iv)(A) for any event that resulted in automatic actuation of an emergency diesel generator.									

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME		2. DOCKET NUMBER	3. LER NUMBER		
Grand Gulf Nuclear Station, Unit 1	☒ 050	00416	YEAR	SEQUENTIAL NUMBER	REV NO.
	☐ 052		2025	002	00

NARRATIVE**Plant Conditions:**

At the time of the event Grand Gulf Nuclear Station (GGNS), Unit 1 was in MODE 1 at 100 percent power and all safety systems were operable.

Description of Event:

On March 15, 2025, at 12:48 CDT, a grid transient caused the 17AC breaker to trip open. In response, the division III emergency diesel generator (EDG) automatically started and repowered the 17AC safety-related electrical bus as designed.

No other safety systems actuated, and no radiological release occurred. All remaining offsite power sources remained energized.

Reportability:

This report is being made in accordance with 10 CFR 50.73(a)(2)(iv)(A) for any event that resulted in automatic actuation of an emergency diesel generator.

Cause(s):

A degraded voltage of the offsite grid caused the event to occur.

Corrective Actions:

Completed Actions:

- After the grid transient passed, the 17AC offsite source feeder breaker was successfully closed in and the division III EDG was secured with no further issues.

Safety Significance:

There were no actual safety consequences associated with this condition. Plant systems responded as designed and the plant remained at 100 percent power.

Previous Similar Events:

None identified.