

Sample standard deviations

100

80

60

40

20

-10

0

10

20

Sample means

N_z

A

tc

W_{dg}

S_W

W_{ph}
 ρ_{ph}
 Λ_{ph}
 W_{fw}