

Sample standard deviations

100

80

60

40

20

-10

-5

0

5

10

15

20

Sample means

S_W

W_dg

W_L

W_m

W_a

W_bda

W_fw

tc

A

N_z