Vehicle Condition Report

en de

POWERED BY PAVE

2022 FIAT DUCATO

VIN # **ZFA25000*2***0128

INSPECTION DATE:
March 19, 2026 @ 10:39 UTC

1
POOR

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
0	7	39
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**	
18	14	

Vehicle Photos

ORIGINAL INSPECTION



Upload Photos

OPTIONAL

No photo

Exterior (15)

LEFT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
2 Left C-Pillar		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4
3 Left Center Panel		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4
1 Left Roof Line		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4
5 Left Roof Line		Has Major Scrape	Scrape that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included
4 Front Left Window Trim		Is Held by Tape	Tape Repair	Replace	3
6 Left Quarter Panel		Has Major Scrape	Scrape that is 300mm or longer or more than 70mm wide	Repair & Refinish	3

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
12 Right Quarter Panel		Has Major Dent - Through Paint	230mm to 255mm	Replace	4
8 Right Quarter Panel		Has Major Scratch - Through Paint	Scratch that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included
9 Right Rocker Panel		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4
13 Rear Right Door		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	3
11 Rear Right Door		Has Severe Dent - Not Through Paint	> 500mm	Replace	Included
10 Rear Right Quarter Side Molding		Missing	Part is missing	Replace	3
7 Right C-Pillar		Has Major Scratch - Through Paint	Scratch that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included

FRONT SIDE

Grade Score 1 Grade Score 4

BACK SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
15 Right C-Pillar		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4
14 Rear Bumper Cover		Has Medium Crack	130mm to 150mm	Replace	3

WINDSHIELD

No damage