Get Voltage

Strobe	Galileo	PIC
	Set Command	Get Ready to read Interrupts Off
	wait	read command
	get ready to read	set response lower 4 bits ADRESH
	read response	wait
	wait	set response upper 4 bits ADRESL
	read response	wait
	wait	set response lower 4 bits ADRESL
	read response	wait
		set response MSG_ACK
	read response	Interrupts On

PING, TOGGLE LED , TOGGLE ADC , RESET

Strobe	Galileo	PIC
	Set Command	Get Ready to read Interrupts Off
	wait	read command & perform task
		set response MSG_ACK
	read response	Interrupts On