Record the fit. Plan the next revision.

FINAL CHECK

- [ ] Case seam is even.
- [ ] Blank is secure.
- [ ] Ports stay accessible.
- [ ] No trapped wiring.
- [ ] Labels match the schematic.

Record print settings, fit issues and measurements. Revise CAD and regenerate matching files.



Next: electrical bring-up and measured testing

Follow technical-assembly-reference.pdf for staged soldering, power checks, SWD, I/O and firmware. A closed case does not establish a working controller.