
04 Secure the controller board.

PARTS / TOOLS

4 × M3 × 6 screws. 4 × M3 washers.

Place a washer under each head, on the PCB. Start all screws and tighten gently in opposite corners. Keep the board flat.



CHECK / No board bowing, bottomed screws or loose hardware.