
05 Wire the positive-side switch loop.





Both J17 contacts are positive power paths. Neither is ground. Verify ON closes the loop and OFF opens it.

J1 supply: pin 1 = +24 V, pin 2 = 0 V/GND (–). Disconnect the source before assembly. OFF does not isolate the input terminal or every external signal.