
09 Close the enclosure by hand.

PARTS / TOOLS

1 completed lid. Board and wiring inspected.

Remove clipped leads and tools. Check switch boots, the display loop and light-guide alignment. Seat the lip into the base without pinching wires.



CHECK / The lid is flush before any case screw is installed.