V0 launch pad skirt Manual

- Can choose where (or not) to mount display.Assembly drawings for each mounting location are identified by colored frames.
  Center display
  Left display
  Right display
  No display

- Choose a divided skirt (all can be printed in V0) or an undivided skirt, and print the inside of the folder you chose.

- STL is produced in sizes designed for ABS/ASA shrinkage, which can cause problems when printed on PLA.

HEAT SET INSERT



If choose center display or no display, assemble 2 pieces.



Test by temporarily inserting PTFE tube, and if this hole is too tight, widen the hole with drill bit.





Only left display



Only right display


M2x10 Self Tapping
x2
x2


M3x10 BHCS
Rubber Foot
Spacer
x2
x2










M3x40 BHCS
M3x10 BHCS



Connect the XH connector before assembling display PCB.

If HX connector is not mounted on the PCB, add it.










M2x10 Self Tapping




M3x6 BHCS



M2x10 Self Tapping






M3x6 BHCS


M2x10 Self Tapping




M3x6 BHCS


M2x10 Self Tapping




M3x6 BHCS

SIDE SKIRT






M3x6 BHCS




M3x6 BHCS

BACK SKIRT







Remove spacers when installing bottom panel.