



R1270/R600 LS = 30 % $T_{src,in} = 50^{\circ}\text{C}$ $C_P = 96.3 \text{ EUR/GJ}_{ex}$ R290/R600a LS = 30 % $T_{src,in} = 50^{\circ}\text{C}$ $C_P = 96.3 \text{ EUR/GJ}_{ex}$ R290/R600a LS = 40 % $T_{src,in} = 60^{\circ}\text{C}$ $C_P = 96.3 \text{ EUR/GJ}_{ex}$



R290/R600a LS = 40 % $T_{src,in} = 60^{\circ}\text{C}$ $C_P = 89.8 \text{ EUR/GJ}_{ex}$ R1270/R600 LS = 50 % $T_{src,in} = 60^{\circ}\text{C}$ $C_P = 89.8 \text{ EUR/GJ}_{ex}$ R1270/R600a LS = 50 % $T_{src,in} = 60^{\circ}\text{C}$ $C_P = 89.8 \text{ EUR/GJ}_{ex}$



COMP1+MOT1 VAL1 IHX COMP2+MOT2 SNK_HX VAL2 marker size $\propto \dot{C}_D$
 SRC_HX